#### Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V Division 3

Once completed, please submit this form either via email to <a href="mailto:info@dwer.wa.gov.au">info@dwer.wa.gov.au</a>, or to the below postal address:

Department of Water and Environmental Regulation Locked Bag 10 Joondalup DC WA 6919

Section A – Licence details			
Licence number:	L5029/1992/11	Licence file number:	2015/002027-6
Licence holder name:	Northern Star (Kanowna) Pty Limited		
Trading as:	KANOWNA BELLE GOLD MINE		
ACN:	010 511 789		
Registered business address:	Kanowna Belle Gold Mine M27/18, 22, 23, 37, 49, 57, 92, 103, 122, 123, 127, 159, 164, 232, 245, 287, 420 and L27/87, 83, 62 KALGOORLIE WA 6430		
Reporting period:	01/01/2021 <b>to</b> 31/12/2021		

Section B – Statement of compliance with licence conditions
---

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

- ☐ Yes please complete:
  - section C;
  - section D (if required); and
  - sign the declaration in Section F.
- - section C;
  - section D (if required);
  - section E; and
  - sign the declaration in Section F.

#### Section C – Statement of actual production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category	Actual production quantity	
5	1,976,297 tonnes	
6	281,291 kL	
44	47,095 tonnes	

Section D – Statement of actual Part 2 waste discharge quantity			
Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.			
Prescribed premises category Actual Part 2 waste discharge quantity			
5	1,976,297 tonnes		
6 281,291 tonnes			

Section E – Details of non-compliance with licence condition				
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.				
Condition no:	5.1.2	Date(s) of non- compliance: 2021		
Details of non-com	pliance:			
	- Methods for sampling and a es located at KCY and WFY a	_	•	
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?	
NOTE – please attac compliance took place	h maps or diagrams to provide i e.	nsight into the precise lo	cation of where the non-	
	suspected environmental imegetation are not likely to impa			
See Figure 1.				
Cause (or suspecte	ed cause) of non-compliance:			
Physical constraints of infrastructure and surrounding vegetation since commissioning of the KAMN represent inherent limitations of the selected monitoring sites. Re-positioning the monitoring sites is not considered a viable option given the power and access limitations and characteristics of these locations (i.e., within light industrial areas and regional bushland).				
It should be noted that NSR does not have land or tenure rights at the locations in which the monitoring stations are sited.				
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:				
Consult with DWER regarding inherent limitations associated with the locations of some of the monitoring sites and develop action plan to address non-compliance.				
Man this non compliance may involve at the DMEDO				
Was this non-compliance previously reported to DWER?  ⊠ Yes, reported in 2020 AACR.				
Reported to DWER verbally Date: / /				
	DWER in writing	Date: 7 /		

Section E – Details of non-compliance with licence condition				
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.				
Condition no:	5.3.1	Date(s) of non- compliance:	2021	
Details of non-comp	pliance:			
ambient air quality	<ul> <li>Method for sampling and an applications (section 2.4 – Ta eorological monitoring equipances.</li> </ul>	able 3, 2.6.1, 3.5.1, 3.5	.2.2 and 3.5.2.3).	
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?	
NOTE – please attac compliance took place	h maps or diagrams to provide i e.	nsight into the precise lo	cation of where the non-	
	suspected environmental imy influence the measured win			
See Figure 1.				
Cause (or suspecte	ed cause) of non-compliance:			
A tree approximately 6m tall is located within 8m of the MEX meteorological monitoring tower. However, the Standard also notes that porous structures such as trees are not likely to have as strong effect on wind flow as a building or other obstruction, and as such the proximity of the tree is not considered likely to significantly influence the measured wind speed and direction at the site.				
It should be noted that NSR does not have land or tenure rights at the locations in which the monitoring stations are sited.				
		·		
monitoring stations		or tenure rights at the	locations in which the	
Monitoring stations  Action taken to mitinon-compliance:  Consult with DWEF	are sited.	or tenure rights at the non-compliance and prons associated with the	locations in which the event recurrence of the	
Action taken to miti non-compliance: Consult with DWEF develop action plan	are sited.  gate any adverse effects of notice and adverse effects of notice and adverse effects of notice.  R regarding inherent limitation to address non-compliance.  De given to the siting limitation	or tenure rights at the non-compliance and prons associated with the	locations in which the event recurrence of the MEX monitoring site and	
Action taken to mitinon-compliance: Consult with DWEF develop action plan Consideration will be in the event of atype	are sited.  gate any adverse effects of notice and adverse effects of notice and adverse effects of notice.  R regarding inherent limitation to address non-compliance.  De given to the siting limitation	or tenure rights at the non-compliance and prens associated with the ns when assessing the	locations in which the event recurrence of the MEX monitoring site and	
Action taken to mitinon-compliance: Consult with DWEF develop action plan Consideration will be in the event of atype	are sited.  gate any adverse effects of not regarding inherent limitation to address non-compliance. The given to the siting limitation ical results.	or tenure rights at the non-compliance and prens associated with the ns when assessing the	locations in which the event recurrence of the MEX monitoring site and	
monitoring stations  Action taken to mitinon-compliance: Consult with DWEF develop action plan Consideration will be in the event of atyp  Was this non-comp	are sited.  gate any adverse effects of not regarding inherent limitation to address non-compliance. The given to the siting limitation ical results.	or tenure rights at the non-compliance and prens associated with the ns when assessing the	locations in which the event recurrence of the MEX monitoring site and	

Section E – Details of non-compliance with licence condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	5.1.3	Date(s) of non- compliance:	10 <sup>th</sup> and 17 <sup>th</sup> September 2021
Details of non-com	pliance:		
September 2021 du	ata loss occurred at the Kambue to equipment failure. The role., valid data was not availabors 5.1.3.	nonthly total valid data	percentage was less than
What was the actua	al (or suspected) environment	tal impact of the non-c	ompliance?
NOTE – please attac compliance took place	ch maps or diagrams to provide in se.	nsight into the precise lo	cation of where the non-
non-compliance as	there was no actual or suspect the prevailing wind direction d 17 <sup>th</sup> of September 2021.		
See Figure 1.			
Cause (or suspecte	ed cause) of non-compliance:		
Pump internal bear	ing failure at the Kambalda m	onitoring station on th	e 10th of September.
Analyser internal power supply failure at the Kambalda monitoring station on the 17th of September.			
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:			
Both faulty units were replaced as soon as practicable and continuous monitoring resumed.			
Was this non-compliance previously reported to DWER?			
Reported to DWER verbally Date: / /			
⊠ Reported to	DWER in writing	Date: 14/10/2021	

Section E – Details of non-compliance with licence condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	3.4.1	Date(s) of non- compliance:	2021
Details of non-com	pliance:		
Red Hill In-pit TSF taken during the 20	& Waldon In-pit TSF tailings 21 calendar year.	surface elevation surve	ey measurements not
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?
	h maps or diagrams to provide i	•	
There was no actua	al or suspected environmenta	al impact resulting from	the non-compliance.
	ere not operational in 2021 (1 nd to Red Hill in January 201		sed to Waldon in
(See Waldon In-pit locations).	TSF monitoring bores map a	and Red Hill In-pit TSF	Monitoring Bores map for
Cause (or suspecte	ed cause) of non-compliance:		
Administrative/ communication error. Supernatant pond elevations were taken in December 2021, as per Condition 3.4.1; However, the requirement to measure the tailings surface elevations was not adequately communicated. The error was identified in January 2022.			
	gate any adverse effects of r	on-compliance and pro	event recurrence of the
non-compliance: Tailings surface elevation survey measurements taken in Jan 2022.			
Was this non-compliance previously reported to DWER?			
⊠ No ☐ Yes			
Reported to DWER verbally			
Reported to	DWER in writing	Date: / /	

Section E – Details of non-compliance with licence condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	3.5.1	Date(s) of non- compliance:	WBH3D - 2021 WBH3S - April 2021 WBH2S - Jan 2021
Details of non-comp	pliance:		
_	el measurements and water o VBH3D - all of 2021, WBH3S		_
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?
NOTE – please attac compliance took plac	h maps or diagrams to provide i e.	nsight into the precise lo	cation of where the non-
	suspected environmental im represented (see <i>Waldon In</i>		•
Additionally, tailings	s discharge ceased to Waldo	n in September 2019.	
Cause (or suspecte	ed cause) of non-compliance:		
	a suspected collapse/blocka	ge in the bore;	
	blockage in the bore; and a lack of safe access followir	ng a heavy rain event.	
TO THE CASE OF CASE ACCESS TO THE THING A FIGURE TO THE COURT.			
Action taken to miti	gate any adverse effects of n	on-compliance and pro	event recurrence of the
non-compliance:			
<ul> <li>WBH3D - NSR monitoring requ</li> </ul>	will seek to amend this Licen	ce condition with a vie	w to removing the
	kage cleared; standing water	level measurements a	nd water quality sampling
<ul> <li>resumed.</li> <li>WBH2S – Standing water level measurements and water quality sampling resumed once</li> </ul>			
access was restored.			
Was this non-compliance previously reported to DWER?			
☐ Reported to	DWER verbally	Date: / /	
⊠ Reported to	DWER in writing	Date: Q1 Report: 23/ 26/05/2021 and 2020	/02/2021, Q2 Report: D AACR - 31/03/21


Section E – Details of non-compliance with licence condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	3.5.1	Date(s) of non- compliance:	April 2021
Details of non-com	pliance:		
_	ility samples were not taken a el at CONCH2 was not under	_	ring bore CONBH2.
	al (or suspected) environmen h maps or diagrams to provide i e.	•	
	suspected environmental im I represented (see <i>BLC-Cons</i>		
Cause (or suspecte	ed cause) of non-compliance:		
Blockages in both bores.			
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the			
non-compliance: Bores unblocked; standing water level measurements and water quality sampling resumed.			
Was this non-compliance previously reported to DWER?			
⊠ Yes, reported in Quarterly Process and Groundwater Monitoring Reports.			
Reported to DWER verbally  Date: / /			
Reported to	DWER in writing	Date: Q2 Report: 26	3/05/2021


Section E – Details of non-compliance with licence condition				
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.				
Condition no:	3.5.1	Date(s) of non- compliance: October 2021		
Details of non-com	pliance:			
	el measurements and water of the state of th		ot taken at groundwater	
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?	
NOTE – please attac compliance took place	h maps or diagrams to provide i e.	nsight into the precise lo	cation of where the non-	
	suspected environmental im I represented (see <i>Red Hill In</i>			
Cause (or suspected	ed cause) of non-compliance:			
Access to the bore was restricted for operational reasons.				
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:				
Standing water level measurements and water quality sampling resumed once access restored.				
Was this non-compliance previously reported to DWER?				
$\square$ No $\boxtimes$ Yes reported in Quarter 4 2021 Process and Groundwater Monitoring Report.				
Reported to	Reported to DWER verbally Date: / /			
Reported to	DWER in writing	Date: Q4 Report: 2	23/11/2021	


Section E – Details of non-compliance with licence condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	3.5.1	Date(s) of non- compliance:	January, February, and July 2021
Details of non-comp	pliance:		
Standing water level measurements and water quality samples were not taken at groundwater monitoring bores:  GWMB11 – January and July 2021;  GWMB23 – January 2021;  GWMB18S & D, GWMB20, KB-KWB79 – February 2021; and  GWMB26 – July 2021.			
	al (or suspected) environmen h maps or diagrams to provide i e.	•	•
Negligible actual or suspected environmental impact. Multiple monitoring bores at the site and groundwater is well represented (see <i>TSF 1-2 monitoring bores</i> map).			
Cause (or suspecte	ed cause) of non-compliance:		
GWMB11 – Damage to headworks of the bore (bent surface casing).  Remaining bores: Lack of safe access following heavy rainfall events.			
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:			
GWMB11 – Damaged rectified; standing water level measurements and water quality sampling resumed.  Remaining bores: Standing water level measurements and water quality sampling resumed once safe access was restored.			
Was this non-compliance previously reported to DWER?			
□ No ⊠ Yes reported in Quarterly Process and Groundwater Monitoring Reports.			
	DWER verbally	Date: / /	
Reported to	DWER in writing	Date: Q1 Report: 23/ 19/08/2021	/02/2021 and Q3 Report:




Figure 1: Goldfields EPP Protected Areas and SO₂ Monitoring Sites









Section F – Declaration			
I / We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular <sup>1</sup> .			
I / We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.			
Signature <sup>2</sup> :		Signature:	
Name: (printed)		Name: (printed)	
Position:		Position:	
Date:	24/03/2022	Date:	
Seal (if signing under seal):			

<sup>&</sup>lt;sup>1</sup> It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

<sup>&</sup>lt;sup>2</sup> AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.