

Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V Division 3

Once completed, please submit this form either via email to info@dwer.wa.gov.au, or to the below postal address:

Department of Water and Environmental Regulation Locked Bag 10 Joondalup DC WA 6919

Annual Audit Compliance Report for

- L8578/2011/1

Section A – Licence details			
Licence number:	L8578/2011/1	Licence file number:	2011/003002-1
Licence holder name:	Regis Resources Limited		
Trading as:	Regis Resources Limited		
ACN:	009 174 761		
Registered business address:	Level 2 516 Hay Street SUBIACO WA 6008		
Reporting period:	1/01/2024 to 31/12 /2024		

Section B - Statement of compliance with licence conditions

Did you comply with all of your Licence conditions during the reporting period? (Please tick the appropriate box)

- ☐ Yes please complete:
 - section C;
 - section D (if required); and
 - · sign the declaration in Section F.

No − please complete:

- section C;
- section D (if required);
- section E; and
- · sign the declaration in Section F.

Section C - Statement of actual production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category	Actual production quantity	
Category 05: Processing or beneficiation of metallic or non-metallic ore	7,670,751 dry tonnes per annual period	
Category 52: Power Generation	20.74 MW per annual period	
Category 73: Bulk storage of chemicals	3,465 m ³	

Section D - Statement of actual Part 2 waste discharge quantity

Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category	Actual Part 2 waste discharge quantity	
Category 06: Mine dewatering	472,695 tonnes per annual period	
Category 53: Sewage Facility (GW)	94 m³ per day	
Category 53: Sewage Facility (MW)	7.09 m³ per day	
Category 89: Putrescible landfill	5,945 m3	

Section E - Details of non-compliance with licence condition

Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.

Dete/e) of non

Condition no:	3.6.1	compliance:	30/11/2025
---------------	-------	-------------	------------

Details of non-compliance:

In November 2024, pH analysis for Russell's Find Pit dewatering was not completed. Due to a wall failure all nonessential personnel could not enter the pit. The mining team assisting with sampling did not record pH. This was not noted at the time, and resampling did not take place.

What was the actual (or suspected) environmental impact of the non-compliance?

NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.

The non-compliance did not result in any environmental impact. Field sampling conducted in February 2025 and showed no notable variances in pH (8.51). The pit water has remained contained and has not been used for any further purposes.

Photo of the incident location:



Cause (or suspected cause) of non-compliance:

The missed sampling parameter was not noted, and resampling of Russell's Find Pit did not occur.

Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:

The internal environmental report monitoring has been adjusted to ensure missed pit parameters are noted and sampling can be rescheduled.

Section E – Details of non-compliance with licence condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Was this non-complian	ce previously reported to DWER?		
⊠ No,			
☐ Reported to DW	/ER verbally	Date: / /	
☐ Reported to DW	/ER in writing	Date:	
	non-compliance with licence con		
Please use a separate reporting period.	page for each condition with which t	the licence holder was non-	compliant at a time during the
Condition no:	3.4.1	Date(s) of non- compliance:	April – December 2024
Details of non-compliar	nce:		
ambient groundwater q	e L8578/2011/1 was amended. Duri juality parameters to include vanadiu not brought into the monitoring scope	um (V). This change to the I	
What was the actual (o	r suspected) environmental impact o	of the non-compliance?	
NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.			
There is no anticipated environmental impact from the non-compliance as localised geology only hosts minor quantities of vanadium. Vanadium has now been included in the quarterly laboratory analysis and will be monitored accordingly.			
Cause (or suspected cause) of non-compliance:			
The addition of ∨anadi	ium was not noted during the integra	ation of the new operating li	cense.
Action taken to mitigate	e any adverse effects of non-complia	ance and prevent recurrenc	e of the non-compliance:
	ded in the laboratory testing regimen , amended licenses are run through		
	ce previously reported to DWER?	<u> </u>	<u> </u>
⊠ No,			
☐ Reported to DWER verbally		Date: / /	
☐ Reported to DWER in writing		Date:	
<u> </u>			
Section E – Details of non-compliance with licence condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	1.2.8	Date(s) of non- compliance:	20/02/2024
Details of non-compliance:			


Section E – Details of non-compliance with licence condition

On the 20th of February 2024, a saline water release from the Erlistoun mine site raw water dam was detected. The estimated total of saline water released was 1,670kL, discharging across approximately 3.08 hectares of native vegetation. Water quality analysis detailed the following: pH: 8.04, TDS: 19,591 mg/L.

What was the actual (or suspected) environmental impact of the non-compliance?

NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.

The impacted area was monitored using both aerial and ground-based photo assessments over a six-month period. The results indicated no significant impact across most of the release area. However, a small section, approximately 0.3 hectares, showed a decline in vegetation health.



Cause (or suspected cause) of non-compliance:

The release occurred due to overflow of the dam wall, the release was detected by a passerby and was immediately shut off by the dewatering team.

Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:

The water being discharged into the dam was immediately isolated to prevent further inflow. The Erlistoun raw water dam has since been decommissioned (see updated aerial image of the decommissioned raw water dam below).

Section E − Details of non-compliance with licence condition Was this non-compliance previously reported to DWER? No, Reported to DWER verbally Reported to DWER in writing Date: 22/02/2024

Section E – Details of non-compliance with licence condition Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period. Date(s) of non-Condition no: 1.2.11 12/07/2024 compliance: Details of non-compliance: At 2:00pm, 12/07/2024, a slow leak was detected at a joint on the Moolart Well to Garden Well Transfer Pipeline. The raw water travelled to the low point where the bund had washed out in recent storm event and into adjacent vegetation. Upon detection of the release, the source of water was promptly shut off and repairs to pipe and bund were completed. The estimated total of raw water released was 6,000 L, intersecting with approximately 0.04 hectares of native vegetation. What was the actual (or suspected) environmental impact of the non-compliance? NOTE - please attach maps or diagrams to provide insight into the precise location of where the non-compliance took The incident covered approximately 0.04 hectares of native vegetation area. There was no observed impact on the health of vegetation within the raw water release area. No priority flora or fauna was impacted. The raw water was tested in field with findings of pH 7.50 and TDS 2476, classing it as brackish water. A map of the release area is

Section E - Details of non-compliance with licence condition provided below. ocation In Vegetation Moolart Well Garden Well Cause (or suspected cause) of non-compliance: The investigation concluded that a section of the fiberglass pipeline had degraded, causing a slow leak under the saddle fitting. The raw water travelled to the low point where the bund had washed out and into adjacent vegetation. Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance: This and other degraded sections of the GW-MW pipeline have now been replaced with new HDPE PVC-pipe and the bunding reinstated. Was this non-compliance previously reported to DWER? No, ☐ Reported to DWER verbally Date: 18/07/2024 Reported to DWER in writing Date:

Section F – Declaration			
I declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular ⁱ .			
I consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.			
Signature ⁱⁱ :		Signature:	
Name: (printed)		Name: (printed)	

Section F – Declaration			
Position:		Position:	
Date:	28/03/2025	Date:	
Seal (if signing under seal):			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

ii AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence

holder.