

Government of Western Australia Department of Water and Environmental Regulation

Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V Division 3

Section A – Licence details			
Licence number:	L8644/2012/1	Licence file number:	2012/002162-1
Licence holder name:	Big Bell Gold Operations Pty Ltd		
Trading as:	Big Bell Gold Operations Pty Ltd		
ACN:	84 090 642 809		
Registered business address:	Office: Level 6, 197 St Georges Tce, Perth, WA, 6000 Post: PO Box 7068, Cloisters Square, WA, 6850		
Reporting period:	01/01/2020 to 31/12/2020		

Section B – Statement of compliance with licence conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

 \Box Yes – please complete:

- section C;
- section D (if required); and
- sign the declaration in Section F.

 \boxtimes No – please complete:

- section C;
- section D (if required);
- section E; and
- sign the declaration in Section F.

Section C – Statement of actual production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category	Actual production quantity	
5 – Processing or beneficiation of metallic or non- metallic ore	1,271,397 tonnes	
6 – Mine dewatering	32,429 tonnes	
64 – Class II putrescible landfill	219 tonnes	

Section D – Statement of actual Part 2 waste discharge quantity

Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category	Actual Part 2 waste discharge quantity	
Water to allow mining of ore	32,429 tonnes	
Tailings	1,647,021 tonnes	

Section E – Details	of non-compliance with I	licence condition	
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	12	Date(s) of non- compliance:	April, July and September 2020
Details of non-compli	ance:		
Three breaches of lic	ence limits were recorded	and reported to DWER dur	ing 2020:
 15 April 2020: Breach of sulphate limit (2000mg/L) in TSF2 monitoring bore TBS3; 13 July 2020: Breach of sulphate limit (2000mg/L) in TSF2 monitoring bore TBS3; and 24 September 2020: Breach of sulphate limit (2000mg/L) in TSF2 monitoring bore TBS3. 			
of the licence limits for the exceedances in a DWER assessment, I reference points surr	or sulphate and TDS at mo April 2019 and a report w L8644/2012/1 was amende	nitoring bore TBS3. DWEF as submitted by BBGO to ed to add the monitoring of a e was further amended on	nd 2020 to advise of exceedance R requested an investigation into DWER in May 2019. Following ambient vegetation quality at four 23 November 2020 to increase
What was the actual	(or suspected) environmer	ntal impact of the non-comp	liance?
NOTE – please attac compliance took plac		wide insight into the precise	location of where the non-
	ronmental impact at this s		bore TBS3. As the exceedance al. TDS and sulphate levels will
Cause (or suspected	cause) of non-compliance	:	
BBGO identified that it is likely that seepage through TBS3 is caused by a bedrock fracture beneath TSF2, and/or surface water flows through TSF. It was also observed that a large volume of water pools at the north-eastern corner of TSF2 following periods of rainfall. It is possible that this water is seeping through the TSF in a north-south direction towards TBS3.			
Action taken to mitiga compliance:	ate any adverse effects of	non-compliance and prever	t recurrence of the non-
In accordance with I electrical geophysica	al investigation around T		commissioned a ground-based tance and depth to which the y 31 October 2021 which:
 describes the relationship between surface water flows and water chemistry at TBS3; advises whether the diversion of surface water upstream of TSF2 has prevented pooling on the north-eastern base of TSF2; 			
required by II	R1; and at further controls for redu	_	netic geophysical investigations , based on the outcomes of the
In the medium to long term (12 months to 2 years), after tailings in TSF2 has sufficiently settled and subsided, 0.5m of waste rock material and 0.2m of laterite and topsoil will be spread on the surface of the TSF. Infrastructure will be removed and the surface will be ripped and revegetated using local provenance flora species. The rehabilitation plan will also include the following where required:			
 Profiling of the outer embankments to reduce long-term erosion risk; Covering of the outer slopes and surfaces with appropriate waste rock; Backfill of all seepage collection trenches and ponds if constructed (and when no longer required); and Ripping and seeding all profiled surfaces with appropriate species. 			

Section E – Details of non-compliance with licence condition		
Rehabilitation of the upper surface will commence when a geotechnical review demonstrates that the strength of the deposited tailings is sufficient to withstand the placement of capping material.		
Was this non-compliance previously reported to DWER?		
Yes, and		
Reported to DWER verbally	Date: / /	
Reported to DWER in writing	Date: Form N1 submitted to DWER on 15 April 2020, 13 July 2020 and 24 September 2020.	

Section F – Declaration

I / We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹.

I / We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature ² :		Signature:	
Name: (printed)		Name: (printed)	
Position:		Position:	
Date:	31/03/2021	Date:	31/03/2021
Seal (if signing under seal):			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.