

# Government of Western Australia Department of Water and Environmental Regulation

# **Annual Audit Compliance Report Form**

Environmental Protection Act 1986, Part V

e Details	<b>建设设置</b>	<b>经制度外更对象</b> 数
L6162/1986/15	Licence file number:	2012/008498
Austral Bricks (WA) Pty Ltd		
079 711 603		
738-780 Wallgrove I HORSLEY PARK N	Road SW 2175	
01/07/2017 to	0 30 / 06 / 2018	
	Austral Bricks (WA 079 711 603 738-780 Wallgrove I HORSLEY PARK N	L6162/1986/15 Licence file number: Austral Bricks (WA) Pty Ltd  079 711 603  738-780 Wallgrove Road HORSLEY PARK NSW 2175

# Section B - Statement of Compliance with Licence Conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

☐Yes – please complete:

- section C;
- · section D if required; and
- · sign the declaration in Section F.

#### ⊠No – please complete:

- · section C;
- section D if required;
- · section E; and
- · sign the declaration at Section F.

## Section C - Statement of Actual Production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed Premises Category	Actual Production Quantity
Cat 41 Clay bricks or ceramic products manufacturing	Commercial in Confidence

## Section D - Statement of Actual Part 2 Waste Discharge Quantity

Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.

Prescribed Premises Category	Actual Part 2 Waste Discharge Quantity
	N/A

Section E - Det	ails of Non-Comp	liance with Licence	Condition
	arate page for each of ereporting period.	condition with which the	e licence holder was non-compliant
Condition no:	5.3.1	Date(s) of no compliance:	
Details of non-con	npliance:		
30 minutes were r	vents that exceeded related to kiln failures st temperatures or po	however, some were	rity of the bypass events exceeding related to differential pressure
	ch maps or diagrams t	ovironmental impact of to provide insight into the	the non-compliance?  precise location of where the non-
either turned off o 1g/sec HF. Bypas Manager and mai	r the push rate was s s activates an alarm ntenance staff. There	slowed to ensure comp which in turn triggers in	t plan was followed and kiln was pliance with the ministerial limit of immediate response from the Kiln ggest that bypass events during the
Cause (or suspec	ted cause) of non-co	mpliance:	1000年100日至日本日本日本日本日本日本日本日本日本日本日本日本日本日本日本日本日本日本
			re related to kiln failures however, st temperatures or power failures.
Action taken to minon-compliance:	itigate any adverse e	ffects of non-complian	nce and prevent recurrence of the
slowed to ensure	compliance with the	ministerial limit of 1g/se	ther turned off or the push rate was sec HF. Bypass activates an alarm ager and maintenance staff.
Was this non-com	pliance previously re	eported to DWER?	
Yes, and			
Reported to	DWER verbally	Date: /	1

## Section F - Declaration

I/We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular<sup>1</sup>. I/We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature <sup>2</sup> :		Signature:	2
Name: (printed)	Robert Bakewell	Name: (printed)	Kemi banaus
Position:	CFO/Director	Position:	BUECTCL
Date:	26/7/18	Date:	26/3/18
Seal (if signing under seal):	1 1		

<sup>&</sup>lt;sup>1</sup> It is an offence under section 112 of the Environmental Protection Act 1986 for a person to give information on this form that to their knowledge is false or misleading in a material particular.

<sup>&</sup>lt;sup>2</sup> AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.