Annual Audit Compliance Report form

Environmental Protection Act 1986, Part V

Section A – Licence Details				
Licence Number:	L4459/1987/13	Licence File Number:	DER2013/000649-1	
Licence Holder:	Argyle Diamonds Limited			
Trading as:	Argyle Diamonds			
ACN:	009 102 621			
Registered address:	Level 8, 1 William Street, PERTH WA 6000			
Reporting period:	1 January to 31 Decembe	r 2022		

Section B – Statement of compliance with licence conditions			
Did y	ou cor	nply with all of your licence conditions during the reporting period?	
Yes		Please complete Sections C, D (if required) and sign the declaration in Section E	
No	\boxtimes	Please complete Sections C, D (if required), F and sign the declaration in Section E	

Section C – Statement of actual production Provide the actual production quantity for this reporting period.*			
12	Screening etc. of material	N/A	
52	Electric power generation	2 MWh	
54	Sewage facility	0 cubic meters per day	
57	Used tyre storage (general)	30 tyres	
63	Class I inert landfill site	138,951 tonnes	
64	Class II putrescible landfill site	775.44 tonnes	
73	Bulk storage of chemical	0 Litres	

^{*}Supporting information will be provided in the relevant conditions of the 2022/2023 Biennial Environment Report

Section D – Statement of actual Part 2 waste discharge quantity			
Provide the	actual Part 2 waste discharge quant	tity for this reporting period.*	
Category	Premises description	Actual Part 2 Waste Discharge Quantity (2021)	
6	Mine dewatering	0 tonnes	

^{*}Supporting information will be provided in the relevant conditions of the 2022/2023 Biennial Environment Report

Section E – Declaration			
I declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular ¹ . I consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.			
Signature ² :	AUDITS (DVVEIX) WEBSITE.		
Name: (printed)			
Position:			
Date:	23/03/2023		

2022 AACR L4459 Page | 1

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder

Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.					
Condition number:					
Details of non-complia	nce:				
Discharge of water from	LCDM (Jacko's [Dam) in excee	edance of criteria as p	er licence condition	34.
What was the actual (c	r suspected) en	vironmental	impact of the non-co	ompliance?	
The actual environmental impact of the incident was considered negligible. No exceedances of licence criteria were observed at downstream sample locations (LCSPRGS & LCLBGS), with water quality results at these downstream locations remaining consistent with historical values.					
Cause (or suspected c	ause) of non-co	mpliance:			
Cessation of mining and dewatering prevented dilution of seepage water in Jacko's Dam, leading to criteria exceedance. Decommissioning of infrastructure and processing facilities as part of closure decreased the need for water onsite, and water that was previously recycled through processing water use had to be discharged. Previous actions from discharge non-compliance indicated the diversion of water from Jacko's Dam to the Pit Lake via the underground portal would prevent further discharge to the environment.					
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the					
Following the initial overflow results (21/2/2022), the sampling regime was increased from fortnightly, as per the Licence criteria, to two samples per week at the discharge point (LCDM) and downstream locations (LCSPRGS and LCLBGS), with daily ongoing field readings collected at LCDM, until overflow ceased. These results were closely monitored for adverse environmental impact downstream.					
Works were undertaken to establish the pumping infrastructure required to divert water from LCDM to the pit lake via the underground portal (as approved) to prevent further wastewater discharge to the environment.					
Was this non-compliance reported to the DWER?					
	WER verbally	Date:			□ No
□ Reported to D	WER in writing	Date:	2/3/2022		

2022 AACR L4459 Page | 2