

Government of Western Australia Department of Water and Environmental Regulation

Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V

Section A – Licence Details				
Licence number:	L5960/1983/11	Licence file number:	2012/005367	
Licence holder:	South32 Worsley Alumina Pty Ltd			
Trading as:	Worsley Alumina Bauxite Mine			
ACN:	008 905 155			
Registered address:	Gastaldo Road, Collie, 6225			
Reporting period:	1/ 7 /2023 to	30 / 6 / 2024		

Section B – Statement of Compliance with Licence Conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

☐ Yes – please complete:

- section C;
- · section D if required; and
- sign the declaration in Section F.

\boxtimes No – please complete:

- section C;
- section D if required;
- section E; and
- sign the declaration at Section F.

Section C – Statement of Actual Production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed Premises Category	Actual Production Quantity	
Cat 5 (Bauxite Mining)	16,538,319 tonnes	

Section D - Statement of Actual Part 2 Waste Discharge Quantity

Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.

Prescribed Premises Category	Actual Part 2 Waste Discharge Quantity
nil	n/a

Section E – Details of Non-Compliance with Licence Condition

Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.

Condition no: Date(s) of non-compliance: 30th November 2023

Details of non-compliance:

There was a 2 week delay in connecting the relocated Dust Monitor (AQ4) to the solar panel power system to meet Condition 19.

Table 7 specified that the required completion date to install the new Dust Monitor was 30th November 2023.


Worsley notified DWER that there would be a delay, but technically this condition was not complied with.

Condition 20 required the submission of the Audit Compliance Report 30 days after the installation date, which was met (submitted 29th December, 2023).

What was the actual (or suspected) environmental impact of the non-compliance?

NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.

Nil impact, as we had a fully functional trailer mounted E Sampler dust monitor at this location recording during this time. No dust data was lost during this period.



Cause (or suspected cause) of non-compliance:

Delays in getting qualified personnel and specialist parts to complete the task. Some of the parts were not known to be faulty at the time of installation.

Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:

Department of Water and Environmental Regulation

Improved planning and scoping of the task, allowing plenty of time to finish commissioning works.				
Was this non-compliance previously reported to DWER?				
☑ Yes,				
☐ Reported to DWER verbally	Date: / /			
☑ Reported to DWER in writing	Date: 20 / 11 / 2023			

Section F - Declaration

 I/We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹. I/We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

 Signature²:
 Signature:

 Name: (printed)
 Name: (printed)

 Position:
 Position:

 Date:
 17 09 24

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.