Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V Division 3

Section A – Licence details				
Licence number:	L8859/2014/1	Licence file number:	DER2014/001998	
Licence holder name:	Mineral Resources Limited			
Trading as:	Mineral Resources Limited			
ACN:	118 549 910			
Registered business address:	Iron Valley Iron Ore Project Mining Tenement M47/1439 and Miscellaneous Licence L47/757 Newman WA 6753			
Reporting period:	01/04/2023 to 31/03/2024			

Section B – Statement of compliance with licence conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

- ☐ Yes please complete:
 - section C;
 - section D (if required); and
 - sign the declaration in Section F.
- \boxtimes No please complete:
 - section C;
 - section D (if required);
 - section E; and
 - sign the declaration in Section F.

Section C – Statement of actual production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category	Actual production quantity
(5) Processing or beneficiation of metallic or non-metallic ore	3,730,305 tonnes
(6) Mine dewatering	16,875,850 tonnes
(89) Putrescible Landfill Site	654.92 tonnes

Section D – Statement of actual Part 2 waste discharge quantity

Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category		Actual Part 2 waste discharge quantity	
		17,189,000 tonnes	
(6) Mine dewatering	(6) Mine dewatering	(Sum of discharges via DDL1, DDL4A, DDL4B and transfers to E1 Pit)	

Department of Water and Environmental Regulation

Section E – Details of non-compliance with licence condition				
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.				
Condition no:	3.4.1	Date(s) of non-compliance:	September 2023 and March 2024	
Details of non-comp	pliance:			
	nt water quality sampling and 2023 and March 2024) and M		ertaken at monitoring point	
An alternative bore (PB23) was sourced to collect a representative sample for PB22, however it was not sampled in March 2024.				
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?	
NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.				
There is not likely to be actual or suspected environmental impact resulting from this non-compliance.				
Cause (or suspected	ed cause) of non-compliance:			
Mine void development The alternative bore	ed cause) of non-compliance: nent encroached on PB22 whee PB23, was unable to be according to the property of geotechnical instability property.	cessed in March 2024		
Mine void development The alternative bord designated an area MB21 is believed to	nent encroached on PB22 when PB23, was unable to be acc	cessed in March 2024 eventing safe access. eted by geotechnical in	due to its location being	
Mine void development The alternative bord designated an area MB21 is believed to is understood to be	nent encroached on PB22 whe PB23, was unable to be according of geotechnical instability probable have potentially been impact	cessed in March 2024 eventing safe access. eted by geotechnical in ling.	due to its location being stability resulting in what	
Mine void development The alternative bord designated an area MB21 is believed to is understood to be Action taken to mitinon-compliance: MinRes is investigated additional bores in subsequently continuors.	nent encroached on PB22 when PB23, was unable to be according to be accorded to b	cessed in March 2024 eventing safe access. eted by geotechnical in ling. on-compliance and presence to provide improportinuous monitoring continuous monitorina monitorina monitorina monitorina monitorina monitorina moni	stability resulting in what event recurrence of the ved flexibility to establish apabilities, and	
Mine void development The alternative bord designated an area and MB21 is believed to is understood to be a complete Action taken to miting non-compliance: MinRes is investigated additional bores in subsequently continuoperations and geometric designations.	nent encroached on PB22 whe PB23, was unable to be accorded of geotechnical instability probable have potentially been impact a blockage preventing sample gate any adverse effects of neuting options to amend the Lical manner that ensures our condity of this environmental co	cessed in March 2024 eventing safe access. Sted by geotechnical in ling. on-compliance and proceed to provide improportinuous monitoring control. Whilst maintaining	stability resulting in what event recurrence of the ved flexibility to establish apabilities, and ng compliance as mining	
Mine void development The alternative bord designated an area and MB21 is believed to is understood to be a compliance: Action taken to miting non-compliance: MinRes is investigated additional bores in subsequently conting operations and geometry and geometric transportations.	nent encroached on PB22 whe PB23, was unable to be accorded to geotechnical instability properties of the potentially been impact a blockage preventing sample gate any adverse effects of neutring options to amend the Lical manner that ensures our conduity of this environmental contechnical conditions evolve.	cessed in March 2024 eventing safe access. eted by geotechnical in ling. on-compliance and properties to provide improportinuous monitoring control. Whilst maintaining mpacted bores with sufficiency and proportinuous monitoring control.	stability resulting in what event recurrence of the ved flexibility to establish apabilities, and ng compliance as mining	
Mine void development The alternative bord designated an area and MB21 is believed to is understood to be a compliance: Action taken to miting non-compliance: MinRes is investigated additional bores in subsequently conting operations and geometry and geometric transportations.	nent encroached on PB22 whe PB23, was unable to be accorded to geotechnical instability properties a blockage preventing sample and adverse effects of neutring options to amend the Lical manner that ensures our conditions of this environmental contechnical conditions evolve. Res will seek to replace the instance of the properties of	cessed in March 2024 eventing safe access. eted by geotechnical in ling. on-compliance and properties to provide improportinuous monitoring control. Whilst maintaining mpacted bores with sufficiency and proportinuous monitoring control.	stability resulting in what event recurrence of the ved flexibility to establish apabilities, and ng compliance as mining	
Mine void development The alternative bord designated an area and MB21 is believed to is understood to be a compliance: Action taken to miting non-compliance: MinRes is investigated additional bores in subsequently conting operations and geo and the aminimum, Minle was this non-compliance. Yes, and	nent encroached on PB22 whe PB23, was unable to be accorded to geotechnical instability properties a blockage preventing sample and adverse effects of neutring options to amend the Lical manner that ensures our conditions of this environmental contechnical conditions evolve. Res will seek to replace the instance of the properties of	cessed in March 2024 eventing safe access. eted by geotechnical in ling. on-compliance and properties to provide improportinuous monitoring control. Whilst maintaining mpacted bores with sufficiency and proportinuous monitoring control.	stability resulting in what event recurrence of the ved flexibility to establish apabilities, and ng compliance as mining	

Department of Water and Environmental Regulation

Section F – Declaration

I / We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹.

I / We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature ² :		Signature:	
Name: (printed)		Name: (printed)	
Position:	General Manager	Position:	
Date:	04/28/2024	Date:	
Seal (if signing under seal):			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.