

Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V Division 3

Section A – Licence details				
Licence number:	5611/1993/11	Licence file number:	DER2014/001167	
Licence holder name:	BHP Iron Ore Pty Ltd			
Trading as:	BHP Iron Ore Pty Ltd			
ACN:	008 700 981			
Registered business address:	Level 1, City Square Brookfield Place 125 St Georges Terrace PERTH WA 6000			
Reporting period:	01/07/2023 to 30/06/2024			

Section B – Statement of compliance with licence conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

 \Box Yes – please complete:

- section C;
- section D (if required); and
- sign the declaration in Section F.

\boxtimes No – please complete:

- section C;
- section D (if required);
- section E; and
- sign the declaration at Section F.

Section C – Statement of actual production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category	Actual production quantity	
5 – Processing or beneficiation of metallic or non-metallic ore	0 Mtpa	
63 – Class I inert landfill site	60 t	
64 – Class II putrescible landfill site	19.8 t	
85 – Sewage facility	2,594 m ³	

Section D – Statement of actual Part 2 waste discharge quantity

Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.

Prescribed Premises Category	Actual Part 2 Waste Discharge Quantity	
6 – Mine dewatering	0	

Department of Water and Environmental Regulation

Section E – Details of non-compliance with licence condition				
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.				
Condition no:	1.3.8	Date(s) of non- compliance:	July 1, 2023-June 31, 2024	
Details of non-compl	liance:			
As per licence Table 1.3.4: The Oily waste evaporation pond is required to be lined with 1.5mm HDPE lined cells to achieve a permeability of <10 ⁻⁹ m/s. BHP identified that the ponds are no longer lined.				
What was the actual	(or suspected) environmenta	al impact of the non-co	mpliance?	
NOTE – please attach	What was the actual (or suspected) environmental impact of the non-compliance? NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.			
Facility has been dee residue in the ponds	commissioned and infrastruc was identified.	ture removed. Evidenc	e of potential residual	
Cause (or suspected cause) of non-compliance: Facility has been decommissioned however residual potential contamination was not remediated when the facility was decommissioned.				
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the				
As per the program of work resulting from the DSI future investigations will be required to develop further understanding of the groundwater conditions.				
Was this non-compliance previously reported to DWER?				
Yes, and				
Reported to D	WER verbally	Date:		
Reported to D	WER in writing	Date: / /		

Department of Water and Environmental Regulation

Section F – Declaration				
I / We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular ¹ .				
I / We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.				
Signature ² :		Signature:		
Name: (printed)		Name: (printed)		
Position:		Position:		
Date:	26/09/2024	Date:		
Seal (if signing under seal):				

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.