

Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V

Section A – Licence Details					
Licence number:	L5972/1992/14	Licence file number:	DER2014/001681		
Licence holder:	Water Corporation				
Trading as:	Bunbury Water Resource Recovery Facility				
ABN:	28 003 434 917				
Registered address:	629 Newcastle Street, LEEDERVILLE, WA 6007				
Reporting period:	01/07/2022 to 30/06/2023				

Section B - Statement of Compliance with Licence Conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

☐Yes - please complete:

- section C;
- · section D if required; and
- · sign the declaration in Section F.

⊠No – please complete:

- · section C;
- · section D if required;
- section E; and
- sign the declaration at Section F.

Section C - Statement of Actual Production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

the state of the s			
Prescribed Premises Category	Actual Production Quantity		
54	11,308 m³/day (details provided in Annual Environmental Report)		
61	5,570.81 tonnes – (details provided in Annual Environmental Report, section 3.3, Condition 4, Table 2 (Licence Amendment dated May 2022). Tankered waste incorporated into Cat 54.		

Section D – Statement of Actual Part 2 Waste Discharge Quantity Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached. Prescribed Premises Category Actual Part 2 Waste Discharge Quantity Not applicable

Section E - Deta	ils of Non-Compliance v	vith Licence Cond	ition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.						
Condition no:	Section 15, Table 8	Date(s) of non- compliance:	1 April to June 30, 2023			
Details of non-compliance:						
June 2023. Flow received for each nas of the 1 July 2 located immediated have been identified Bunbury WRRF. Be	rates from April to June 20 nonth over the last 3 years d 023, inflow data is being rely before the entrance of the das being able to record pack calculations can be applicated pumpstation will continuation.	23 are estimations bue to malfunction of interest of the coorded from wastever Bunbury WRRF. Toump runtimes of flowing to work out the interest of the coordinate of the interest of the interest of the coordinate of the coordinat	WRRF between 1 April to 30 based on average flow rates inflow meters. Water transfer pump stations was that are directed into the inflow rates. Recording inflow researched the facility gates can be			
What was the actua	al (or suspected) environmer	ntal impact of the non	-compliance?			
NOTE – please attac	h maps or diagrams to provide e.	insight into the precise	location of where the non-			
design capacity for	the facility.					
	ed cause) of non-compliance					
	s not accurately recording flo					
non-compliance:	•					
Inflow meters at the	e facility gates are expected	to be replaced by 202	24.			
Was this non-comp	liance previously reported to	DWER?				
X No						
Yes, and						
☐ Reported to	DWER verbally	Date: / /				
Reported to	DWER in writing					

Section F - Declaration

I/We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹. I/We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature ² :		Signature:	
Name: (printed)		Name: (printed)	
Position:	General Manager Operations	Position:	
Date:	15 SEPT 2023	Date:	
Seal (if signing under seal):			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.