

# **Annual Audit Compliance Report Form**

Environmental Protection Act 1986, Part V

Section A – Licence Details				
Licence number:	L5997/1991/11	Licence file number:	DEC14180	
Licence holder:	Water Corporation			
Trading as:	Mandurah No.2 (Halls Head) Wastewater Treatment Plant			
ABN:	28 033 434 917			
Registered address:	629 Newcastle Street, LEEDERVILLE, WA 6007			
Reporting period:	01 / 07 / 2023 to 30 / 06 / 2024			

# Section B – Statement of Compliance with Licence Conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

 $\Box$  Yes – please complete:

- section C;
- section D if required; and
- sign the declaration in Section F.

 $\boxtimes$  No – please complete:

- section C;
- section D if required;
- section E; and
- sign the declaration at Section F.

### Section C – Statement of Actual Production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed Premises Category	Actual Production Quantity	
54 – sewage facility	3,630 m3/d (details in Annual Environmental Report)	

#### Section D – Statement of Actual Part 2 Waste Discharge Quantity

Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.

Prescribed Premises Category	Actual Part 2 Waste Discharge Quantity	

Section E – Details of Non-Compliance with Licence Condition					
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.					
Condition no:	3	Date(s) of non- compliance:	17/12/2021; 01/07/2024		
Details of non-compliance:					
Condition 3 of L5997/199/11 requires recovered screenings and grit from the inlet works to be stored in an enclosed and sealed bin stored within a bunded hardstand area which returns leachate to the start of the treatment process. This area at Halls Head WRRF is not bunded.					
What was the actua	al (or suspected) environ	mental impact of the nor	n-compliance?		
<b>NOTE</b> – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.					
Grit and screens are located on a hardstand area that drains to a sump, which returns any leachate to the head of the plant. The lack of bunding at the entrance to this area does not pose any additional risk of spills or overflows to the environment, therefore, there is no suspected or actual environmental impact.					
any additional risk	of spills or overflows to the	ne environment, therefore	e, there is no suspected or		
any additional risk actual environment	of spills or overflows to the		e, there is no suspected or		
any additional risk actual environment Cause (or suspected Grit and screenings contained in the bir which drains to the immediately downs stage this was an a installed.	of spills or overflows to the calimpact. ed cause) of non-compliants bins are located on a gens, however, should any return liquor pump static stream of the inlet works acceptable mitigation of a	ance: raded hardstand area. Le surplus leachate escape on. From here, leachate i at the head of the plant. any environmental risks, t	eachate is primarily the area it drains to a sump, s returned to the bioselector, It was determined at design therefore bunding was not		
any additional risk actual environment Cause (or suspecte Grit and screenings contained in the bir which drains to the immediately downs stage this was an a installed. Action taken to miti	of spills or overflows to the calimpact. ed cause) of non-compliants bins are located on a gens, however, should any return liquor pump static stream of the inlet works acceptable mitigation of a	ance: raded hardstand area. Le surplus leachate escape on. From here, leachate i at the head of the plant. any environmental risks, t	eachate is primarily the area it drains to a sump, s returned to the bioselector, It was determined at design		
any additional risk actual environment Cause (or suspected Grit and screenings contained in the bir which drains to the immediately downs stage this was an a installed. Action taken to miti non-compliance: An amendment of t	of spills or overflows to the al impact. ed cause) of non-compliants bins are located on a gens, however, should any return liquor pump static stream of the inlet works acceptable mitigation of a figate any adverse effects	ance: raded hardstand area. Le surplus leachate escape on. From here, leachate is at the head of the plant. any environmental risks, t s of non-compliance and o reflect how grit and scree	eachate is primarily the area it drains to a sump, s returned to the bioselector, It was determined at design therefore bunding was not		
any additional risk a actual environment Cause (or suspecte Grit and screenings contained in the bir which drains to the immediately downs stage this was an a installed. Action taken to miti non-compliance: An amendment of t onsite. This will be	of spills or overflows to the cal impact. ed cause) of non-compliants bins are located on a grass, however, should any return liquor pump static stream of the inlet works acceptable mitigation of a grate any adverse effects the Licence is required to	ance: raded hardstand area. Le surplus leachate escape on. From here, leachate i at the head of the plant. any environmental risks, t of non-compliance and o reflect how grit and scre next Licence renewal.	eachate is primarily the area it drains to a sump, s returned to the bioselector, It was determined at design therefore bunding was not prevent recurrence of the		
any additional risk a actual environment Cause (or suspecte Grit and screenings contained in the bir which drains to the immediately downs stage this was an a installed. Action taken to miti non-compliance: An amendment of t onsite. This will be	of spills or overflows to the al impact. ed cause) of non-compliants bins are located on a gene, however, should any return liquor pump static acceptable mitigation of a space any adverse effects the Licence is required to requested as part of the space of the spac	ance: raded hardstand area. Le surplus leachate escape on. From here, leachate i at the head of the plant. any environmental risks, t of non-compliance and o reflect how grit and scre next Licence renewal.	eachate is primarily the area it drains to a sump, s returned to the bioselector, It was determined at design therefore bunding was not prevent recurrence of the		
any additional risk a actual environment Cause (or suspected Grit and screenings contained in the bir which drains to the immediately downs stage this was an a installed. Action taken to mition non-compliance: An amendment of to onsite. This will be Was this non-comp	of spills or overflows to the al impact. ed cause) of non-compliants bins are located on a gene, however, should any return liquor pump static acceptable mitigation of a space any adverse effects the Licence is required to requested as part of the space of the spac	ance: raded hardstand area. Le surplus leachate escape on. From here, leachate i at the head of the plant. any environmental risks, t of non-compliance and o reflect how grit and scre next Licence renewal.	eachate is primarily the area it drains to a sump, s returned to the bioselector, It was determined at design therefore bunding was not prevent recurrence of the		

# Section F – Declaration

I / We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular<sup>1</sup>.

I / We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature <sup>2</sup> :		Signature:	
Name: (printed)		Name: (printed)	
Position:		Position:	
Date:	24/09/2024	Date:	
Seal (if signing under seal):			

<sup>&</sup>lt;sup>1</sup> It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

 $<sup>^{2}</sup>$  AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.