

# Government of Western Australia Department of Water and Environmental Regulation

## **Annual Audit Compliance Report Form**

Environmental Protection Act 1986, Part V

Section A – Licence Details				
Licence number:	L5997/1992/11	Licence file number:	DEC14180	
Licence holder:	Water Corporation			
Trading as:	Mandurah No.2 (Halls Head) Water Resource Recovery Facility			
ACN:	28 033 434 917			
Registered address:	629 Newcastle Street, LEEDERVILLE, WA 6007			
Reporting period:	01/07/2022 <b>to</b> 30/06/2023			

Continu D CA	lakamant af	Committee	an with I inco	an Conditions
Section B – St	atementoi	Compilant	ce willi Licei	ice Conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

- ☐ Yes please complete:
  - section C;
  - · section D if required; and
  - · sign the declaration in Section F.

### ⋈ No – please complete:

- · section C;
- section D if required;
- section E; and
- sign the declaration at Section F.

# Section C – Statement of Actual Production Provide the actual production quantity for this reporting period. Supporting documentation is to be attached. Prescribed Premises Category Actual Production Quantity 3,479 m3/d (details in Annual Environmental Report)

17 f 11 : 1 : 1 0 : 1
uantity for this reporting period. Supporting
Actual Part 2 Waste Discharge Quantity

Section E - Deta	ils of Non-Compliance v	vith Licence Cond	lition	
	ate page for each condition		ce holder was non-compliant	
Condition no:	1.2.3	Date(s) of non- compliance:	17/12/2021; 01/07/2022	
Details of non-comp	oliance:			
be stored in an enc	.5997/199/11 requires recov losed and sealed bin stored t of the treatment process. T	within a bunded har	dstand area which returns	
What was the actua	al (or suspected) environme	ntal impact of the nor	n-compliance?	
	h maps or diagrams to provide			
leachate to the hea	of spills or overflows to the e	unding at the entranc	e to this area does not pose	
Cause (or suspecte	ed cause) of non-compliance	i:		
contained in the bir which drains to the immediately downs		lus leachate escape From here leachate is ne head of the plant.	the area drains to a sump, s returned to the bioselector, It was determined at design	
Action taken to miti	gate any adverse effects of	non-compliance and	prevent recurrence of the	
An amendment of	the Licence is required to re requested as part of the nex		reenings are being managed	
Was this non-comp	liance previously reported to	DWER?		
⊠ Yes, and				
☐ Reported to I	DWER verbally	Date: / /		
x☐ Reported to	DWER in writing	2021-22 AER and AACR		

### Section F - Declaration

I / We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular<sup>1</sup>.

I / We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature <sup>2</sup> :		Signature:	
Name: (printed)		Name: (printed)	
Position:	General Manager Operations	Position:	
Date:	13 SEPT ZOZ3	Date:	
Seal (if signing under seal):			

<sup>&</sup>lt;sup>1</sup> It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

<sup>&</sup>lt;sup>2</sup> AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.