

Government of Western Australia Department of Water and Environmental Regulation

Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V Division 3

Once completed, please submit this form either via email to info@dwer.wa.gov.au, or to the below postal address:

Department of Water and Environmental Regulation Locked Bag 10 Joondalup DC WA 6919

Section A – Licence details			
Licence number:	L6146/1990/11	Licence file number:	AB32325522619N
Licence holder name:	Meneghello Galvanizing Pty Ltd		
Trading as:	Mgalv		
ACN:	008 897 729		
Registered business address:	46 Rogers Way Landsdale WA 6065		
Reporting period:	01 / 07 / 2023	to 30 / 06 / 202	.4

Section B – Statement of compliance with licence conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

- ☐ Yes please complete:
 - section C;
 - section D (if required); and
 - sign the declaration in Section F.
- - section C;
 - section D (if required);
 - section E; and
 - sign the declaration in Section F.

Section C - Statement of actual production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category	Actual production quantity
48A Metal Finishing (Hot-Dip Galvanizing)	20,591.433 T

Section D – Statement of actual Part 2 waste discharge quantity

Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category	Actual Part 2 waste dis	charge quantity
48A Metal Finishing (Hot-Dip Galvanizing)	Pickle Liquor: 667.1T	Sludges: 115.840T

Section E – Details of non-compliance with licence condition				
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.				
Condition no:	1	Date(s) of non- compliance:	30.05.2023	
Details of non-comp	pliance:			
Fugitive Emissions				
Reference ICMS 70	0154			
The below is the wo	ording from the complaint			
that morning at 8:3	rk plume of smoke from stack 0am 31/05/2023. Due to fog, moke. Also advised loud ope has photos."	smoke is staying arou	nd and covering Darch in	
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?	
NOTE – please attac compliance took place	h maps or diagrams to provide i e.	nsight into the precise lo	cation of where the non-	
Emissions escapino	g form the galvanizing shed			
Cause (or suspecte	ed cause) of non-compliance:			
	pen during galvanizing or em		moving loads into the	
galvanizing shed or from the galvanizing shed to the fettling shed				
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:				
Toolbox all shift supervisors to ensure that all doors to the galvanizing shed are closed during				
galvanizing.				
Was this non-compliance previously reported to DWER?				
⊠ Reported to	DWER verbally	Date: 30.05.2023		
Reported to	DWER in writing	Date: / /		

Section E – Details of non-compliance with licence condition				
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.				
Condition no:	2	Date(s) of non- compliance:	30.05.2023	
Details of non-com	pliance:			
Noise complaint				
Reference ICMS 7	0154			
Below is the wording	ng from the complaint			
Also advised loud of photos."	pperating noises from premise	es outside of operating	hours. Advised she has	
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?	
NOTE – please attac compliance took place	h maps or diagrams to provide i e.	nsight into the precise lo	cation of where the non-	
Noise levels higher	than normal			
Cause (or suspecte	ed cause) of non-compliance:			
	ne root cause as we were ope		do on nightshift and are	
always conscious o	of noise levels and our neighb	oors		
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:				
Production to toolbox all supervisors on the importance of keeping the doors always closed and				
to try and reduce the noise levels wherever possible on afternoon/Nightshift.				
Was this non-compliance previously reported to DWER?				
⊠ Yes, and Reference ICMS 70154				
□ Reported to	DWER verbally	Date: 30.05.2023		
☐ Reported to	DWER in writing	Date: / /		

Section E – Details of non-compliance with licence condition				
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.				
Condition no:	3	Date(s) of non- compliance:	31.05.2023	
Details of non-com	pliance:			
Fugitive Emissions				
Reference ICMS 70	0154			
The below is the we	ording from the complaint			
that morning at 8:3	rk plume of smoke from stack 0am 31/05/2023. Due to fog, moke. Also advised loud ope has photos."	smoke is staying arou	nd and covering Darch in	
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?	
NOTE – please attac	h maps or diagrams to provide i e.	nsight into the precise lo	cation of where the non-	
Emissions escaping	g form the galvanizing shed			
Cause (or suspected	ed cause) of non-compliance:			
Possible door left open during galvanizing or emissions escaping while moving loads into the galvanizing shed or from the galvanizing shed to the fettling shed				
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the				
non-compliance: Production to toolbox all supervisors on the importance of keeping the doors always closed and				
to try and reduce the noise levels wherever possible on afternoon/Nightshift.				
Was this non-compliance previously reported to DWER?				
□ Reported to	DWER verbally	Date: 31.05.2023		
☐ Reported to	DWEP in writing	Date: / /		

Department of Water and Environmental Regulation

Section E – Details of non-compliance with licence condition			
Please use a separat a time during the	rate page for each condition verting period.	vith which the licence h	holder was non-compliant
Condition no:	4	Date(s) of non- compliance:	29.04.2024
Details of non-comp	oliance:		
Section 72 Waste of	lischarge		
What was the actua	al (or suspected) environment	tal impact of the non-c	ompliance?
NOTE – please attac compliance took place	h maps or diagrams to provide i e.	nsight into the precise lo	cation of where the non-
Fugitive Emissions	after galvanizing kettle explo	sion	
Cause (or suspecte	ed cause) of non-compliance:		
Molten zinc on the	concrete floor, burning water	hose on the ground	
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the			
non-compliance: All orders to be checked to ensure that they are vented correctly to prevent explosions in the			
kettle.	,		τ
Was this non-compliance previously reported to DWER?			
⊠ Yes, and as per	email and site visit from		
⊠ Reported to	DWER verbally	Date: 29.04.2024	
☐ Reported to	DWER in writing	Date: / /	

Section F – Declaration

I / We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹.

I / We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature ² :		Signature:	
Name: (printed)		Name: (printed)	
Position:	Senior Operations Manager	Position:	HSEQ Superintendent
Date:	17.07.2024	Date:	17.07.2024
Seal (if signing under seal):			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.