### Government of Western Australia Department of Water and Environmental Regulation



## Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V

Once completed, please submit this form either via email to <u>info-der@dwer.wa.gov.au</u>, or to the below postal address:

Department of Water and Environmental Regulation Locked Bag 10 Joondalup DC, WA, 6919

Licence number:	L6248/1991/8	Licence file number:	DER2013/001029
Licence holder:	Water Corporation		
Trading as:	Karratha No.1 Wastewater Treatment Plant		
ACN:	28 033 434 917		
Registered address:	629 Newcastle Street, LEEDERVILLE, WA 6007		
Reporting period:	01/07/2021 to 30 June 2022		

### Section B - Statement of Compliance with Licence Conditions

Did you comply with all your licence conditions during the reporting period? (Please tick the appropriate box)

#### □ Yes – please complete:

- section C.
- section D if required; and
- sign the declaration in Section F.

#### ⊠ No – please complete:

- section C.
- section D if required.
- section E; and
- sign the declaration at Section F.

### Section C – Statement of Actual Production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed Premises Category	Actual Production Quantity	
54	3,458 m³/day	

Section D - Statement of Actual Pa	rrt 2 Waste Discharge Quantity
Provide the actual Part 2 waste discharg documentation is to be attached.	e quantity for this reporting period. Supporting
Prescribed Premises Category	Actual Part 2 Waste Discharge Quantity
Not Applicable	

	parate page for each co he reporting period.	ondition with which the licent	ce nolder was non-complian
Condition no:	1.3.5 (b)	Date(s) of non- compliance:	14/06/2022
Details of non-co	mpliance:		
Collapsed and su internal Environm		on pond embankments we	re observed during an
What was the ac	tual (or suspected) env	ironmental impact of the no	n-compliance?
NOTE – please att compliance took pl		provide insight into the precise	e location of where the non-
	cted cause) of non-com ns, erosion and genera	npliance: al wear and tear over time.	
Weather conditio	ns, erosion and genera		prevent recurrence of the
Weather conditio Action taken to m non-compliance: Asset deficiency	ns, erosion and genera nitigate any adverse eff has been registered inf	al wear and tear over time.	base for assessment and
Weather conditio Action taken to m non-compliance: Asset deficiency prioritization to fix	ns, erosion and genera nitigate any adverse eff has been registered inf	al wear and tear over time. ects of non-compliance and to our asset deficiency datal ing and collapsed concrete s	base for assessment and
Weather conditio Action taken to m non-compliance: Asset deficiency prioritization to fix Was this non-cor	ns, erosion and genera nitigate any adverse eff has been registered in and repair the subsid	al wear and tear over time. ects of non-compliance and to our asset deficiency datal ing and collapsed concrete s	base for assessment and
Weather condition Action taken to mean to mean taken tak	ns, erosion and genera nitigate any adverse eff has been registered in and repair the subsidi	al wear and tear over time. ects of non-compliance and to our asset deficiency datal ing and collapsed concrete s	base for assessment and

Condition no:	1.3.5(d)	Date(s) of non- compliance:	14/06/2022
Details of non-co	ompliance:		
		on the treatment pond embanl loating debris were also obser	
What was the ac	tual (or suspected) er	nvironmental impact of the nor	n-compliance?
NOTE – please att compliance took p		to provide insight into the precise	location of where the non-
Nil environmenta	l impact likely becaus	se of this non-compliance.	
	cted cause) of non-co		
Routine vegetatio	on maintenance had	been done however a quick pr	olific regrowth of vegetation
Routine vegetatio		been done however a quick pr	olific regrowth of vegetation
Routine vegetatio	on maintenance had	been done however a quick pr	olific regrowth of vegetation
Routine vegetatio	on maintenance had	been done however a quick pr	olific regrowth of vegetation
Routine vegetationas been exacer	on maintenance had bated by unexpected	been done however a quick pr	
Routine vegetation has been exacer Action taken to n non-compliance:	on maintenance had bated by unexpected	been done however a quick pr rains in May 2022. effects of non-compliance and	prevent recurrence of the
Routine vegetation has been exacer Action taken to n hon-compliance: A once off round whilst a botanist	on maintenance had bated by unexpected hitigate any adverse e of slash and spray of has been engaged to	been done however a quick pr rains in May 2022. effects of non-compliance and rganised in addition to the plar do a weed survey and propos	prevent recurrence of the nned routine maintenance
Routine vegetation has been exacer Action taken to n hon-compliance: A once off round whilst a botanist	on maintenance had bated by unexpected nitigate any adverse e of slash and spray of	been done however a quick pr rains in May 2022. effects of non-compliance and rganised in addition to the plar do a weed survey and propos	prevent recurrence of the nned routine maintenance
Routine vegetation has been exacer Action taken to n hon-compliance: A once off round whilst a botanist	on maintenance had bated by unexpected hitigate any adverse e of slash and spray of has been engaged to	been done however a quick pr rains in May 2022. effects of non-compliance and rganised in addition to the plar do a weed survey and propos	prevent recurrence of the nned routine maintenance
Routine vegetation has been exacer Action taken to n hon-compliance: A once off round whilst a botanist	on maintenance had bated by unexpected hitigate any adverse e of slash and spray of has been engaged to	been done however a quick pr rains in May 2022. effects of non-compliance and rganised in addition to the plar do a weed survey and propos	prevent recurrence of the nned routine maintenance
Routine vegetation has been exacer Action taken to n hon-compliance: A once off round whilst a botanist Weed Managem	on maintenance had bated by unexpected hitigate any adverse e of slash and spray of has been engaged to	been done however a quick pr rains in May 2022. effects of non-compliance and rganised in addition to the plar o do a weed survey and propos inder review	prevent recurrence of the nned routine maintenance
Routine vegetation has been exacer Action taken to n non-compliance: A once off round whilst a botanist Weed Managem	on maintenance had bated by unexpected nitigate any adverse e of slash and spray of has been engaged to ent plan is currently u	been done however a quick pr rains in May 2022. effects of non-compliance and rganised in addition to the plar o do a weed survey and propos inder review	prevent recurrence of the nned routine maintenance
Routine vegetation has been exacer Action taken to n non-compliance: A once off round whilst a botanist Weed Managem Was this non-cor	on maintenance had l bated by unexpected nitigate any adverse e of slash and spray of has been engaged to ent plan is currently u mpliance previously re	been done however a quick pr rains in May 2022. effects of non-compliance and rganised in addition to the plar o do a weed survey and propos inder review	prevent recurrence of the nned routine maintenance

Condition no:       1.3.6(d)       Details of non-compliance:       14/06/2022         Details of non-compliance:       A hole was observed on the eastern side fence next to a previously patched up/fixed hole a site environmental inspection, likely a result of vandalism       What was the actual (or suspected) environmental impact of the non-compliance?         What was the actual (or suspected) environmental impact of the non-compliance?       NOTE – please attach maps or diagrams to provide insight into the precise location of where the compliance took place.         Nil environmental impact likely as a result of this non-compliance.       Cause (or suspected cause) of non-compliance:         Likely a result of vandalism       Action taken to mitigate any adverse effects of non-compliance and prevent recurrence non-compliance:         Discussed with TL and Operations Manager who organised repairs to be done by a cor	
A hole was observed on the eastern side fence next to a previously patched up/fixed he a site environmental inspection, likely a result of vandalism What was the actual (or suspected) environmental impact of the non-compliance? NOTE – please attach maps or diagrams to provide insight into the precise location of where the compliance took place. Nil environmental impact likely as a result of this non-compliance. Cause (or suspected cause) of non-compliance: Likely a result of vandalism	
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence non-compliance:	
NOTE – please attach maps or diagrams to provide insight into the precise location of where the compliance took place.         Nil environmental impact likely as a result of this non-compliance.         Cause (or suspected cause) of non-compliance:         Likely a result of vandalism         Action taken to mitigate any adverse effects of non-compliance and prevent recurrence non-compliance:	le during
Cause (or suspected cause) of non-compliance: Likely a result of vandalism Action taken to mitigate any adverse effects of non-compliance and prevent recurrence non-compliance:	non-
Likely a result of vandalism Action taken to mitigate any adverse effects of non-compliance and prevent recurrence non-compliance:	
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence non-compliance:	
non-compliance:	
non-compliance:	
Discussed with TL and Operations Manager who organised repairs to be done by a cor	
	of the
	1.1.1.1
	1.1.1.1
Was this non-compliance previously reported to DWER?	
Yes No Reported to DW/ER verbally Dete: / /	
Reported to DWER verbally    Date:    /      Reported to DWER in writing    Date:    1    / 9    / 2022	1.1.1.1

is not false or misle	e information in this Annua	lar <sup>1</sup> . I/We consent to	Report is true and correct and the Annual Audit Compliance tion's (DER) website.
Signature <sup>2</sup> :		Signature:	
Name: (printed)		Name: (printed)	
Position:		Position:	
Date:	25/8/2022	Date:	
Seal (if signing under seal):			

<sup>&</sup>lt;sup>1</sup> It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

<sup>&</sup>lt;sup>2</sup> AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.