Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V

| Section A – Licence Details | | | | |
|-----------------------------|--|----------------------|------------------|--|
| Licence number: | L6420/1988/14 | Licence file number: | DER2015/002506-1 | |
| Licence holder: | Kalgoorlie Consolidated Gold Mines Pty Ltd | | | |
| Trading as: | | | | |
| ACN: | 97 009 377 619 | | | |
| Registered address: | Northern Star Resources Ltd Level 4, 500 Hay Street, Subiaco WA 6008 (previously Level 1, 388 Hay Street, Subiaco WA 6008) | | | |
| Reporting period: | 1 January 2022 to 31 December 2022 | | | |

Section B – Statement of Compliance with Licence Conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

 \Box Yes – please complete:

- section C;
- section D if required; and
- sign the declaration in Section F.

\boxtimes No – please complete:

- section C;
- section D if required;
- section E; and
- sign the declaration at Section F.

Section C – Statement of Actual Production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

| Prescribed Premises Category | Actual Production Quantity |
|---|----------------------------|
| 5 – Processing or beneficiation of metallic or non-metallic ore | 12,823,278 tonnes |
| 12 – Screening etc. of material | 1,549,678 tonnes |
| 54 – Sewerage facility | 13.9 m3/day |
| 63 – Class I inert landfill site | 192.3 tonnes |
| 64 – Class II putrescible landfill site | 0 tonnes |

Section D – Statement of Actual Part 2 Waste Discharge Quantity

Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.

| Proscribad Pramisas (Catadory | Actual Part 2 Waste Discharge Quantity |
|---|---|
| 5 – Processing or beneficiation of metallic or non-metallic ore | 12,490,420 tonnes |

Department of Water and Environmental Regulation

| Section E – Deta | ils of Non-Compliance w | ith Licence Conditi | on | | | | |
|---|--|--------------------------------|------------------|--|--|--|--|
| Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period. | | | | | | | |
| Condition no: | 5, 37 | Date(s) of non- compliance: | 31 December 2022 | | | | |
| Details of non-com | Details of non-compliance: | | | | | | |
| | 37. The licence holder shall submit a construction compliance document to the CEO within 90 days of completion of each stage of the works listed in Table 1, Table 3, Table 4, Table 5 (Condition 5) , Table 6 and Table 7). | | | | | | |
| It has been identified that the submission of the Construction Compliance Reports for the construction of Stage 1 (East and West Cells) of the Kaltails TSF, and Stage 2 of the Fimiston I TSF have been delayed beyond the 90 days as stipulated in Condition 37 of the Licence. The delay has been due both to internal and external resourcing, exacerbated by the impact of the COVID-19 pandemic. The reports were submitted to DWER on the 27 March 2023. | | | | | | | |
| KCGM can advise that the TSF facilities were inspected and verified by the Engineer of Record following the lift construction. Additionally, KCGM provides Annual TSF Audit Reports for the Fimiston (inclusive of Kaltails TSF) and Gidji TSFs to DWER in the Annual Environment Report. | | | | | | | |
| What was the actual (or suspected) environmental impact of the non-compliance? NOTE – please attach maps or diagrams to provide insight into the precise location of where the non- compliance took place. | | | | | | | |
| There was no actual or suspected environmental impact of the potential non-compliance with the Licence. KCGM can advise that the TSF facilities were inspected and verified by the Engineer of Record following the lift construction. Additionally, KCGM provides Annual TSF Audit Reports for the Fimiston (inclusive of Kaltails TSF) and Gidji TSFs to DWER in the Annual Environment Report. | | | | | | | |
| Cause (or suspected cause) of non-compliance: | | | | | | | |
| The delay has been due both to internal and external resourcing, exacerbated by the impact of the COVID-19 pandemic. | | | | | | | |
| Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance: | | | | | | | |
| Obligations and tasks associated with the requirement to submit Construction Compliance Reports within the required timeframe has been reviewed by KCGM and amended where required. An annual audit of DWER licence conditions will continue to be conducted. | | | | | | | |
| Was this non-compliance previously reported to DWER? | | | | | | | |
| ✓ Yes, and | | | | | | | |
| ✓ Reported to D | WER verbally | Date: 27 March 2023 | 3 | | | | |
| ✓ Reported to D | WER in writing | Date: 27 March 2023 | 3 | | | | |
| | | | | | | | |

Department of Water and Environmental Regulation

| Section F – Declaration | | | | |
|--|-----------------|-----------------|--|--|
| I/We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular ¹ . I/We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website. | | | | |
| Signature ² : | | Signature: | | |
| Name: (printed) | | Name: (printed) | | |
| Position: | General Manager | Position: | | |
| Date: | 29/03/2023 | Date: | | |
| Seal (if signing under seal): | | | | |

¹ It is an offence under section 112 of the Environmental Protection Act 1986 for a person to give information

on this form that to their knowledge is false or misleading in a material particular. ² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.