Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V Division 3

Once completed, please submit this form either via email to info@dwer.wa.gov.au, or to the below postal address:

Department of Water and Environmental Regulation Locked Bag 10 Joondalup DC WA 6919

Section A – Licence details				
Licence number:	L6465/1989/10	Licence file number:	2010/007470-1~1	
Licence holder name:	Alcoa of Australia Limited			
Trading as:				
ACN:	004 879 298			
Registered business address:	181-205 Davy Street BOORAGOON WA 6154			
Reporting period:	01/01/2023 to 31/12/2023			

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

- ☐ Yes please complete:
 - section C;
 - section D (if required); and
 - sign the declaration in Section F.
- \boxtimes No please complete:
 - section C;
 - section D (if required);
 - section E; and
 - sign the declaration in Section F.

Section C – Statement of actual production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category	Actual production quantity	
Category 05 - Processing or beneficiation of metallic or non-metallic ore	9,894,872 tonnes of bauxite crushed.	

Section D – Statement of actual Part 2 waste discharge quantity

Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.

dodinionation to to be attached.				
Prescribed premises category	Actual Part 2 waste discharge quantity			
N/A	N/A			

Department of Water and Environmental Regulation

Section E – Details of non-compliance with licence condition				
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.				
Condition no:	W1	Date(s) of non- compliance:	24 th – 26 th April 2023	
Details of non-com	pliance:			
During three days of wet weather (24/4/2023 - 10.6mm, 25/4/2023 - 7.0mm and the 26/4/2023 - 75.8mm), the Arundel Anpress Pre-treatment overflow sump (secondary shotcrete sump) discharged an unknown volume of untreated water from the emergency overflow pipe into the Arundel Stormwater sump system. The Arundel Anpress Pre-treatment sumps had been pumped out in preparation for the rain event in the days prior however were inadequate to hold the volume of water entering the system. This event resulted in stormwater released to the unsealed environment (Arundel Stormwater 1				
& 2), which was likely to contain hydrocarbons. This volume of water would have flowed from Stormwater 1 & 2 to Arundel Pond 3/4/5, which was sampled and verified as not triggering hydrocarbon discharge levels.				
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?	
NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.				
There is no known environmental impact from this non-compliance. Water sampling of the licensed Arundel Ponds confirmed water quality within the limits specified in the Licence (sampling as per Table 5 and water quality result within the limits specified in Table 6 of the Licence).				
Cause (or suspected cause) of non-compliance:				
Inadequate stormwater storage.				
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:				
Upgrades to the Anpress pre-treatment sumps and stormwater collection ponds have been approved in the Licence amendment received 20/02/24. These upgrades will be installed in accordance with licence requirements.				
Was this non-compliance previously reported to DWER? Not applicable.				
☐ Yes, and				
Reported to	DWER verbally	Date: / /		
☐ Reported to	DWER in writing	Date: / /		

Department of Water and Environmental Regulation

Section F – Declaration

I / We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹.

I / We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature ² :		Signature:	
Name: (printed)		Name: (printed)	
Position:	Interim Vice President Operations - Australia	Position:	VP - Asset Management
Date:	25/03/2024	Date:	25/03/2024
Seal (if signing under seal):			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.