

Government of Western Australia Department of Water and Environmental Regulation

Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V

Licence number:	L6796/1991/13	Licence file number:	DER2016/000585-1
Licence holder:	Water Corporation		
Trading as:	Narrogin Water Resource Recovery Facility		
ABN:	28 003 434 917		
Registered address:	629 Newcastle Street, LEEDERVILLE, WA 6007		
Reporting period:	01/07/2022 to 30/06/2023		

Section B – Statement of Compliance with Licence Conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

□Yes – please complete:

- section C;
- section D if required; and
- sign the declaration in Section F.

⊠No – please complete:

- section C;
- section D if required;
- section E; and
- sign the declaration at Section F.

Section C – Statement of Actual Production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed Premises Category	Actual Production Quantity	
54	925 m³/day (details in Annual Report)	

Section D - Statement of Actual Part 2 Waste Discharge Quantity

Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.

Prescribed Premises Category	Actual Part 2 Waste Discharge Quantity	

Please use a sep	parate page for each condition	with which the licent	ce holder was non-complian
at a time during t	he reporting period.		
Condition no:	Condition 1.2.2, Table 1.2.2	Date(s) of non- compliance:	2022_23
Details of non-co	ompliance:		
	cifies that the sewage must under only in the primary pond and not t		tion ponds (plural). There is
NOTE – please att	tual (or suspected) environments ach maps or diagrams to provide		
compliance took pl	lace.		
	mental impact in consequence of		ondary pond is low.
	cted cause) of non-compliance		
Cause (or suspe			
Cause (or susper The aerator in the Action taken to m	cted cause) of non-compliance	: me time ago and not re	eplaced.
Cause (or suspen The aerator in the Action taken to m non-compliance:	cted cause) of non-compliance secondary pond was removed so nitigate any adverse effects of n	e: me time ago and not re non-compliance and	eplaced.
Cause (or suspen The aerator in the Action taken to m non-compliance: A current planning	cted cause) of non-compliance secondary pond was removed so	e: me time ago and not re non-compliance and	eplaced.
Cause (or suspen The aerator in the Action taken to m non-compliance: A current planning aeration.	cted cause) of non-compliance secondary pond was removed so nitigate any adverse effects of n	e: me time ago and not re non-compliance and om inlet works to wetl	eplaced.
Cause (or suspen The aerator in the Action taken to m non-compliance: A current planning aeration.	cted cause) of non-compliance secondary pond was removed so nitigate any adverse effects of project is reviewing treatment fro	e: me time ago and not re non-compliance and om inlet works to wetl	eplaced.

r lease use a set	parate page for each condi	tion with which the licent	ce holder was non-compliant
	the reporting period.		
Condition no:	1.2.3, Table 1.2.3	Date(s) of non- compliance:	2022_23
Details of non-co	ompliance:		
The condition spec Table 1.2.3 The table includes		ed/treated within vessels/c anks (no longer operational nd 2 (aerator no longer in p)
What was the ac	tual (or suspected) enviror	nmental impact of the no	n-compliance?
NOTE – please att compliance took pl	ach maps or diagrams to pro lace.	vide insight into the precise	e location of where the non-
Cause (or suspe	cted cause) of non-complia	ance:	
The clarifier humus	s tanks have been replaced w		ere has been an oversight in
The clarifier humus not amending the l	s tanks have been replaced w	vith the trickling filter and th	
The clarifier humus not amending the l	s tanks have been replaced w icence previously.	vith the trickling filter and th	
The clarifier humus not amending the I The aerator in the Action taken to m	s tanks have been replaced w icence previously.	vith the trickling filter and th d some time ago and not re	eplaced.
The clarifier humus not amending the I The aerator in the Action taken to m non-compliance: A current planning	s tanks have been replaced w icence previously. secondary pond was remove nitigate any adverse effects	vith the trickling filter and th d some time ago and not re s of non-compliance and	prevent recurrence of the
The clarifier humus not amending the I The aerator in the Action taken to m non-compliance: A current planning aeration.	s tanks have been replaced w icence previously. secondary pond was remove nitigate any adverse effects	vith the trickling filter and th d some time ago and not re s of non-compliance and nt from inlet works to wetl	eplaced.
The clarifier humus not amending the I The aerator in the Action taken to m non-compliance: A current planning aeration.	s tanks have been replaced w icence previously. secondary pond was remove nitigate any adverse effects project is reviewing treatmen	vith the trickling filter and th d some time ago and not re s of non-compliance and nt from inlet works to wetl	prevent recurrence of the

Section F – Declaration

I/We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹. I/We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature ² :		Signature:	
Name: (printed)		Name: (printed)	
Position:	General Manager Operations	Position:	
Date:	26 SEPT ZOZ3	Date:	
Seal (if signing under seal):			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.