

A01nnual Audit Compliance Report Form

Environmental Protection Act 1986, Part V Division 3

Once completed, please submit this form either via email to info@dwer.wa.gov.au, or to the below postal address:

Department of Water and Environmental Regulation Locked Bag 10 Joondalup DC WA 6919

Section A – Licence details				
Licence number:	L7210/1997/10	Licence file number:	DER2010/010225	
Licence holder name:	MushroomExchange Pty Ltd			
Trading as:	Mushroom Exchange			
ACN:	004 527 440			
Registered business address:	271-279 Robinsons Rd RAVENHALL VIC 302			
Reporting period:	01 / 01 / 2022 to 31 / 12 / 2022			

Section B – Statement of compliance with licence conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

- ☐ Yes please complete:
 - section C:
 - section D (if required); and
 - sign the declaration in Section F.
- No − please complete:
 - section C;
 - section D (if required);
 - section E; and
 - sign the declaration in Section F.

Section C - Statement of actual production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category	Actual production quantity	
67A – Compost Manufacturing & Soil Blending	32,934 metric tonne.	

Section D - Statement of actual Part 2 waste discharge quantity

Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting

documentation is to be attached.	
Prescribed premises category	Actual Part 2 waste discharge quantity

Section E – Details of non-compliance with licence condition				
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.				
Condition no:	5	Date(s) of non- compliance:	N/A	
Details of non-com	pliance:			
Hardstand Remediation – The hardstand has been damaged in multiple areas during the reporting year. This was caused by the use of specialised equipment required for the compost-making process.				
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?	
NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.				
There is no known	environmental impact of the	breach.		
Cause (or suspecte	ed cause) of non-compliance:	:		
The machinery and equipment are unique to the mushroom industry. Unfortunately, the equipment's design, weight, and use caused the damage to the hardstand.				
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:				
 Mushroom Exchange continuously monitored and repaired the hardstand when required. Equipment modifications were made to prevent any further damage to the hardstand as soon as it became apparent the damage had occurred. All site staff were re-trained in best practice machinery operation, including monitoring any potential impact. 				
Was this non-compliance previously reported to DWER?				
☐ Yes, and				
☐ Reported to	DWER verbally	Date: / /		
□ Reported to	DWER in writing	Date: / /		

Section F - Declaration

I / We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹.

I / We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature ² :		Signature:	
Name: (printed)		Name: (printed)	
Position:	Chief Financial Officer	Position:	Company Secretary
Date:	31/03/2023	Date:	31/03/2023
Seal (if signing under seal):			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.