



Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V

Section A – Licence Details			
Licence number:	L7910/2003/6	Licence file number:	2012/006888
Licence holder:	MacPhersons Resources Ltd		
Trading as:			
ACN:	139 357 967		
Registered address:	109 Maritana Street Kalgoorlie WA 6430		
Reporting period:	01 / 07 / 2023 to 30 / 06 / 2024		

Section B – Statement of Compliance with Licence Conditions
Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)
<input type="checkbox"/> Yes – please complete: <ul style="list-style-type: none">• section C;• section D if required; and• sign the declaration in Section F.
<input checked="" type="checkbox"/> No – please complete: <ul style="list-style-type: none">• section C;• section D if required;• section E; and• sign the declaration at Section F.

Section C – Statement of Actual Production	
Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.	
Prescribed Premises Category	Actual Production Quantity
Category 5 – Processing or beneficiation of metallic or non-metallic ore	0

Section D – Statement of Actual Part 2 Waste Discharge Quantity	
Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.	
Prescribed Premises Category	Actual Part 2 Waste Discharge Quantity
Category 5 – Processing or beneficiation of metallic or non-metallic ore	0

Section E – Details of Non-Compliance with Licence Condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	9	Date(s) of non-compliance:	August 2023
Details of non-compliance:			
<p>In accordance with Condition 9 (Table 4) of the Licence, monitoring of groundwater from the four TSF2 monitoring bores must be undertaken every six months.</p> <p>Generally, six-monthly monitoring is undertaken in February and August each year.</p> <p>During the reporting period, although field analysis was undertaken in August 2023, water quality samples were not collected from the TSF2 monitoring bores.</p>			
What was the actual (or suspected) environmental impact of the non-compliance?			
<p>NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.</p> <p>Nil</p>			
Cause (or suspected cause) of non-compliance:			
<p>Misunderstanding of monitoring requirements pertaining to groundwater abstraction (5C) Licence and Prescribed Premises Licence. Monitoring only undertaken for 5C Licence.</p>			
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:			
<p>Site personnel now aware that monitoring requirements for both licenses is obligatory.</p> <p>The correct sampling regime was undertaken in February 2024.</p>			
Was this non-compliance previously reported to DWER?			
<input type="checkbox"/> Yes, and			
<input type="checkbox"/> Reported to DWER verbally		Date: / /	
<input type="checkbox"/> Reported to DWER in writing		Date: / /	

Section F – Declaration

I/We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹. I/We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature ² :		Signature:	
Name: (printed)		Name: (printed)	
Position:		Position:	
Date:	15/08/2024	Date:	
Seal (if signing under seal):			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.