Annual Audit Compliance Report form

Environmental Protection Act 1986, Part V

Section A – Licence Details						
Licence Number:	L8232/2008/2	Licence File Number:	DER2013/001103			
Licence Holder:	Pilbara Iron Company (Services) Pty Ltd					
Trading as:	Rio Tinto Iron Ore					
ACN:	107 210 248					
Registered address:	L18, Central Park. 152-158 St. Georges Terrace, PERTH WA 6000					
Reporting period:	1 January 2018 to 31 December 2018					

Section B – Statement of compliance with licence conditions

Did you comply with all of your licence conditions during the reporting period?		
Yes		Please complete Sections C, D (if required) and sign the declaration in Section E
No	\boxtimes	Please complete Sections C, D (if required), F and sign the declaration in Section E

Section C – Statement of actual production

Provide the actual production quantity for this reporting period.*

Category	Premises description	Actual production quantity (2018)		
5	Processing or beneficiation of metallic or non-metallic ore	45,422,495 tonnes		
12	Screening, etc. of material	9,500 tonnes		
54	Sewage facility	242 cubic metres per day		
64	Class II putrescible landfill site	2,610 tonnes		
73	Bulk storage of chemicals, etc	2,205 cubic metres		

*Supporting information provided in the relevant conditions of the 2018 Annual Environment Report

Section D – Statement of actual Part 2 waste discharge quantity Provide the actual Part 2 waste discharge quantity for this reporting period.* Category Premises description Actual Part 2 Waste Discharge Quantity (2018)

6 Mine dewatering 1,599,817 tonnes

*Supporting information provided in the relevant conditions of the 2018 Annual Environment Report

Section E – Declaration				
I declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular ¹ . I consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.				
Signature ² :				
Name: (printed)	Steve Badenhorst			
Position:	General Manager, Brockman Region – Iron Ore			
Date:	23/04/2019			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder

Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period. Condition number: 3 Date(s) of non-compliance: 22/10/2018 -31/12/2018 Details of non-compliance: 22/10/2018 -31/12/2018 No cumulative volumes of treated wastewater discharged from the Central Facilities WWTP were recorded between 22 October and 31 December 2018. What was the actual (or suspected) environmental impact of the non-compliance? What was no environmental impact as a result of this non-compliance. Water quality samples were collected as required by condition 4. Cause (or suspected cause) of non-compliance: The flowmeter measuring cumulative volumes failed. Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance: A replacement flowmeter was ordered and installed. Was this non-compliance reported to the DWER? Yes: Reported to DWER verbally Date: Image: Image	Section F – Details of non-compliance with licence condition					
Details of non-compliance: No cumulative volumes of treated wastewater discharged from the Central Facilities WWTP were recorded between 22 October and 31 December 2018. What was the actual (or suspected) environmental impact of the non-compliance? There was no environmental impact as a result of this non-compliance. Water quality samples were collected as required by condition 4. Cause (or suspected cause) of non-compliance: The flowmeter measuring cumulative volumes failed. Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance: A replacement flowmeter was ordered and installed. Was this non-compliance reported to the DWER? Yes: Reported to DWER verbally Date: No		age for each co	ndition with which the licence holde	er was non-compliant	at a time during	
No cumulative volumes of treated wastewater discharged from the Central Facilities WWTP were recorded between 22 October and 31 December 2018. What was the actual (or suspected) environmental impact of the non-compliance? There was no environmental impact as a result of this non-compliance. Water quality samples were collected as required by condition 4. Cause (or suspected cause) of non-compliance: The flowmeter measuring cumulative volumes failed. Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance: A replacement flowmeter was ordered and installed. Was this non-compliance reported to the DWER? Section Taken to DWER verbally Date: No	Condition number:	3	Date(s) of non-compliance:	22/10/2018 -31/12/2	2018	
between 22 October and 31 December 2018. What was the actual (or suspected) environmental impact of the non-compliance? There was no environmental impact as a result of this non-compliance. Water quality samples were collected as required by condition 4. Cause (or suspected cause) of non-compliance: The flowmeter measuring cumulative volumes failed. Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance: A replacement flowmeter was ordered and installed. Was this non-compliance reported to the DWER? Section Taken to DWER verbally Date:	Details of non-complia	nce:				
There was no environmental impact as a result of this non-compliance. Water quality samples were collected as required by condition 4. Cause (or suspected cause) of non-compliance: The flowmeter measuring cumulative volumes failed. Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance: A replacement flowmeter was ordered and installed. Was this non-compliance reported to the DWER? Pes: Reported to DWER verbally Date:						
required by condition 4. Cause (or suspected cause) of non-compliance: The flowmeter measuring cumulative volumes failed. Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance: A replacement flowmeter was ordered and installed. Was this non-compliance reported to the DWER? Pes: Reported to DWER verbally Date: No	What was the actual (o	r suspected) er	vironmental impact of the non-c	ompliance?		
The flowmeter measuring cumulative volumes failed. Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance: A replacement flowmeter was ordered and installed. Was this non-compliance reported to the DWER? Yes: Reported to DWER verbally Date:						
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance: A replacement flowmeter was ordered and installed. Was this non-compliance reported to the DWER? Yes: Reported to DWER verbally Date:	Cause (or suspected c	ause) of non-co	ompliance:			
non-compliance: Image: Compliance in the image: Complise in the image: Compliance in the image: Comp	The flowmeter measuring cumulative volumes failed.					
A replacement flowmeter was ordered and installed. Was this non-compliance reported to the DWER? Yes: Reported to DWER verbally Date:	_	e any adverse (effects of non-compliance and pr	event recurrence of	the	
Yes: Reported to DWER verbally Date: No	A replacement flowmeter was ordered and installed.					
Reported to DWER verbally Date: No	Was this non-compliance reported to the DWER?					
	Reported to D				🖂 No	