Annual Audit Compliance Report form

Environmental Protection Act 1986, Part V

Section A – Licence Details						
Licence Number:	L8431/2010/2	Licence File Number:	DEC8830-02			
Licence Holder:	Pilbara Iron Pty Ltd					
Trading as:	Rio Tinto Iron Ore					
ACN:	107 216 535					
Registered address:	L18, Central Park. 152-158 St. Georges Terrace, PERTH WA 6000					
Reporting period:	1 January 2018 to 31 December 2018					

Section B – Statement of compliance with licence conditions

Did y	Did you comply with all of your licence conditions during the reporting period?		
Yes		Please complete Sections C, D (if required) and sign the declaration in Section E	
No	\square	Please complete Sections C, D (if required), F and sign the declaration in Section E	

Section C – Statement of actual production

Provide the actual production quantity for this reporting period.*

Category Premises description		Actual production quantity (2018)	
52	Electrical power generation	230 Megawatts	

*Supporting information provided in the relevant conditions of the 2018 Annual Environment Report

Section D - Statement of actual Part 2 waste discharge quantity Provide the state Part 2 waste discharge quantity for this reporting period.* Category Premises description Actual Part 2 Waste Discharge Quantity (2018) Not Applicable - no categories relevant to Part 2 waste discharge quantity.

*Supporting information provided in the relevant conditions of the 2018 Annual Environment Report

Section E – Declaration				
I declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular ¹ . I consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.				
Signature ² :				
Name: (printed)	Amit Bareja			
Position:	General Manager, Core Services (acting) – Iron Ore			
Date:	30/04/2019			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder

Section F – Details of non-compliance with licence condition							
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.							
Condition number:	2	Date(s) of non-compliance:	21 – 22 June 2018				
Details of non-complia	Details of non-compliance:						
GTG8 engine was unavailable for the June exhaust stack emission testing due to works requiring the turbine to be offline for several weeks.							
What was the actual (o	r suspected) er	nvironmental impact of the non-c	ompliance?				
There was no environmental impact as a result of this non-compliance.							
Cause (or suspected ca	ause) of non-co	ompliance:					
The prolonged repair period of the turbine coincided with the scheduling of the June bi-annual stack test which was unable to be rescheduled.							
Action taken to mitigat	e any adverse o	effects of non-compliance and pr	event recurrence of	the			
The non-compliance was due to an unforeseen breakdown which required parts of the engine to be sent overseas. GTG8 was able to be tested during the December 2018 stack testing program and results within range.							
Was this non-compliance reported to the DWER?							
Yes: Reported to D Reported to D		Date: Date:		🛛 No			