

Government of Western Australia Department of Water and Environmental Regulation

Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V

Once completed, please submit this form either via email to <u>info-der@dwer.wa.gov.au</u>, or to the below postal address:

Department of Water and Environmental Regulation Locked Bag 10 JOONDALUP, WA 6919

Licence number:	L8442/2010/3	Licence file number:	2010/002927	
Licence holder:	Electricity Networks Corporation			
Trading as:	Western Power			
ACN:	18 540 492 861			
Registered address:	363 Wellington Street, Perth WA 6000			
Reporting period:	01/07/2021 to 30/06/2022			

Section B – Statement of Compliance with Licence Conditions

Did you comply with all your licence conditions during the reporting period? (please tick the appropriate box)

Yes – please complete:

- section C;
- section D if required; and
- sign the declaration in Section F.

\boxtimes No – please complete:

- section C;
- section D if required;
- section E; and
- sign the declaration at Section F.

Section C – Statement of Actual Production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed Premises Category	Actual Production Quantity	
61: Liquid waste facility	153,823.63L of new and used oil was received.	

Section D – Statement of Actual Part 2 Waste Discharge Quantity Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.				
61: Liquid waste facility	Not applicable.			

Section E – Deta	ils of Non-Complian	ce with Licence Condition	
Please use a separ during the reporti		dition with which <mark>th</mark> e license h	nolder was non-compliant at a time
Condition no:	1.2.5	Date(s) of non- compliance:	2021/22
Details of non-con	npliance:		
loaded or unloaded off position. However, it was fou in oil seeping throug	s that the shut-off valve s d. The oil store shut-off v and that the asphalt drive gh the cracks in the even	eway within oil storage area is da t of an oil spill	is activated while any oil is being it was confirmed as being in the shut maged which could potentially result damages which have occurred since.
		ronmental impact of the non- rovide insight into the precise loo	compliance? cation of where the non-compliance
observed with rainv	vater subsidence. Howev	er, the potential exists for oil see	epage to occur should a spill develop.
Cause (or suspected	ed cause) of non-comp	liance:	
Cracks in asphalt.			
Action taken to m compliance:	itigate any adverse eff	ects of non-compliance and p	revent recurrence of the non-
Repair damaged asp rainwater drain.	bhalt to ensure that no p	otential exists for any spilled oil t	o seep through into the soil or
	pliance previously rep	orted to DWER?	
Yes, and			
	o DWER verbally o DWER in writing	Date: / / Date: / /	

Section F – Declaration

I / We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹.

I / We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature ² :		Signature:	
Name: (printed)		Name: (printed)	
Position:		Position:	
Date:	17/8/2022	Date:	
Seal (if signing under seal):			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.