

Government of Western Australia Department of Water and Environmental Regulation

Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V Division 3

Once completed, please submit this form either via email to <u>info@dwer.wa.gov.au</u>, or to the below postal address:

Department of Water and Environmental Regulation Locked Bag 10 Joondalup DC WA 6919

Section A – Licence	Section A – Licence details						
Licence number:	L8553/2011/1	Licence file number:					
Licence holder name:	BHP Billiton Petroleum Pty Ltd						
Trading as:	BHP Billiton Petroleum Pty Ltd						
ACN:	39 006 923 879						
Registered business address:	125 St Georges Terrace, Perth, Western Australia, 6000						
Reporting period:	01/04/2020 to 31/03/2	021					

Section B – Statement of compliance with licence conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

 \boxtimes Yes – please complete:

- section C;
- section D (if required); and
- sign the declaration in Section F.

\Box No – please complete:

- section C;
- section D (if required);
- section E; and
- sign the declaration in Section F.

Section C – Statement of actual production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category	Actual production quantity
10	1,440,188.224 tonnes
34	527.069 tonnes

Department of Water and Environmental Regulation

Section D – Statement of actual Part 2 waste discharge quantity

Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting

documentation is to be attached.	documentation is to be attached.							
Prescribed premises category	Actual Part 2 waste discharge quantity							
Section E – Details of non-compliance wi	th licence condition							
· · · · ·	with which the licence holder was non-compliant							
Condition no:	Date(s) of non- compliance:							
Details of non-compliance:								
What was the actual (or suspected) environmen	tal impact of the non-compliance?							
NOTE – please attach maps or diagrams to provide i compliance took place.	nsight into the precise location of where the non-							
Cause (or suspected cause) of non-compliance								
Action taken to mitigate any adverse effects of r	on-compliance and provent recurrence of the							
non-compliance:								
Was this non compliance providually reported to	DWER2							
Was this non-compliance previously reported to	DWER!							
Yes, and Reported to DWER verbally	Date: / /							

Department of Water and Environmental Regulation

Section E – Details of non-compliance with licence condition					
Reported to DWER in writing	Date: / /				

Section F – Declaration

I / We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹.

I / We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature ² :		Signature:	
Name: (printed)		Name: (printed)	
Position:	Manager Field Operations	Position:	Manager HSE
Date:	27/04/2021	Date:	27/04/2021
Seal (if signing under seal):			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.

Supporting Information for Licence Compliance Macedon

Form AR1:	Monitoring of point sour	rce emissions to ai					
Emission point	Parameter	Result (mg/m³) ¹	Results (g/s)	Averaging period	Method	Sample date & times	Licence Condition Met (Y/N)
-	Nitrogen oxides	<7	<0.1	60 minutes	USEPA 7E		Y
A1	Carbon monoxide	<7	<0.1	60 minutes	USEPA 10	15-10-2020 10:02	Y
SGC A	Volatile organic compounds	<2	<0.03	60 minutes	USEPA 25A		Y
	Nitrogen oxides	<7	<0.1	60 minutes	USEPA 7E	15-10-2020 07:35	Y
A2 SGC B	Carbon monoxide	<7	<0.14	60 minutes	USEPA 10		Y
	Volatile organic compounds	<2	<0.03	60 minutes	USEPA 25A		Y
	Nitrogen oxides	<7	<0.1	60 minutes	USEPA 7E		Y
A3 SGC C	Carbon monoxide	<7	<0.1	60 minutes	USEPA 10	14-10-2020 12:42	Y
	Volatile organic compounds	<2	<0.03	60 minutes	USEPA 25A		Y

Emission point	Parameter	Result (mg/m³) ¹	Results (g/s)	Averaging period	Method	Sample date & times	Licence Conditions Met (Y/N)
	Nitrogen oxides	66	0.11	60 minutes	USEPA 7E		Y
A4	Carbon monoxide	310	0.52	60 minutes	USEPA 10	14-10-2020 08:35	Y
GTG A	Volatile organic compounds (as Methane)	410	0.68	60 minutes	USEPA 25A		Y
A5 GTG B	Nitrogen oxides	68	0.13	60 minutes	USEPA 7E		Y
	Carbon monoxide	240	0.44	60 minutes	USEPA 10	14-10-2020 07:09	Y
	Volatile organic compounds	220	0.41	60 minutes	USEPA 25A		Y
	Nitrogen oxides	NA	NA	60 minutes	USEPA 7E		NA
A6 GTG C	Carbon monoxide	NA	NA	60 minutes	USEPA 10	Offline	NA
	Volatile organic compounds	NA	NA	60 minutes	USEPA 25A		NA
	Nitrogen oxides	93	0.16	60 minutes	USEPA 7E		Y
A7 GTG D	Carbon monoxide	230	0.4	60 minutes	USEPA 10	13-10-2020 16:03	Y
	Volatile organic compounds	280	0.48	60 minutes	USEPA 25A		Y

Note 1: All units are referenced to STP dry and corrected to 15% O2



Date:

Emission point	Parameter	Result (m³)	Averaging period	Frequency	Method	Licence Conditions Met (Y/N)
A8	Cumulative volume flared	238,334	Annual	Continuous	NGER (Measurement) Determination 2008	Y
A9	Cumulative volume flared	348,612	Annual	Continuous	NGER (Measurement) Determination 2008	Y

=B

All monitoring was undertaken in compliance to conditions 1.2.2, 2.2, 3.1.2, 3.1.3, 3.1.4 and 3.2.

All air emission results (except cumulative flared volumes) were obtained from Ektimo report number R009565r (Annual Emissions Monitoring 2020 Macedon Gas Facility).

Cumulative Flare Volumes were obtained from BHP Petroleum's Enterprise Upstream system.

Signed on behalf of BHP Billiton Petroleum Pty Ltd:



Date:

Licence: L8553/2011/1 Form: GR1 Name: Monitoring of Groundwater Licensee: Period:

BHP Billiton Petroleum Pty Ltd 01 April 2020 – 31 March 2021

Emission point	Parameter	Result	Unit	Averaging period	Method	Sample date & times	Licence Conditions Met (Y/N)
	рН	7.28	pH Unit		EA005P		Y
	Standing water level	-0.320	mAHD				Y
	Electrical conductivity	59.90	mS/cm		EA010P		Y
	Total Petroleum Hydrocarbons	<0.050	mg/L		EP080/071		Y
	Benzene	<0.001	mg/L	_	EP080		Y
	Toluene	<0.002	mg/L		EP080		Y
	Ethylbenzene	<0.002	mg/L		EP080	13.10.2020	Y
MB01	Xylene	<0.002	mg/L	Spot Sample	EP080	15:00	Y
	Mercury	<0.0001	mg/L		EG035F		Y
	Lead	<0.005	mg/L		EG020F		Y
	Arsenic	<0.005	mg/L		EG020F		Y
	Copper	0.008	mg/L		EG020F		Y
	Nickel	0.008	mg/L	1	EG020F		Y
	Cadmium	<0.0005	mg/L]	EG020F		Y
	Chromium	0.038	mg/L		EG020F		Y

Signed on behalf of BHP Billiton Petroleum Pty Ltd:

Date:

Emission point	Parameter	Result	Unit	Averaging period	Method	Sample date & times	Licence Conditions Met (Y/N)
	рН	7.70	pH Unit		EA005P		Y
	Standing water level	-0.220	mAHD				Y
	Electrical conductivity	58.90	mS/cm		EA010P		Y
	Total Petroleum Hydrocarbons	0.090	mg/L		EP080/071		Y
	Benzene	<0.001	mg/L	-	EP080		Y
	Toluene	<0.002	mg/L		EP080		Y
	Ethylbenzene	<0.002	mg/L		EP080	40.40.0000	Y
MB02	Xylene	<0.002	mg/L	Spot Sample	EP080		Y
	Mercury	<0.0001	mg/L		EG035F		Y
	Lead	<0.005	mg/L		EG020F		Y
	Arsenic	<0.005	mg/L		EG020F		Y
	Copper	0.021	mg/L		EG020F		Y
	Nickel	0.017	mg/L	-	EG020F		Y
	Cadmium	<0.0005	mg/L		EG020F		Y
	Chromium	0.024	mg/L		EG020F		Y

All monitoring was undertaken in compliance to conditions 1.2, 1.3, 3.1.1, 3.1.2, and 3.8. All groundwater results were obtained in the Macedon Gas Plant Groundwater Quality Monitoring Report – 11 November 2020 (Worley, 2020)



Licence: L8553/2011/1 Licensee: BHP Billiton Petroleum Pty Ltd

Period: 01 April 2020 - 31 March 2021

Condition 5.2.1: The Licensee shall submit to the Director at the Contact Address an Annual Environmental Report within 28 calendar days after of the end of the annual period. The report shall contain the information listed in Table 5.2.1 in the format or form specified in that table.

Table 5.2.1:	Table 5.2.1: Annual Environmental Report								
Condition or Table (if relevant)	Parameter	Format or Form ¹	BHP Petroleum Comments						
-	Summary of any failure or malfunction of any pollution control equipment or any incidents that have occurred during the annual period and any action taken	None specified	On 7 Feb 2021, during an inspection of F-317B Sales gas filter (located at Dampier to Bunbury Natural Gas Pipeline) metering skid, an unmanned metering station 67 km from the Macedon site) was found to be leaking from the vessel lid flange. Leak detection readings using a portable gas detector were 35%LEL at 200 mm distance. Gas volume 36 m ³ . Vessel isolated and the lip seal was pressured up to achieve a better seal, this reduced the leak substantially. Vessel isolated and notification raised to replace Lipseal. This incident was reported to DMIRS in BHP Monthly Recordable Environmental Incident Report Form for Macedon dated February 2021.						
Table 2.2.2	Limit exceedances	N1	Form N1 is not Required as no limit exceedances were measured during the reporting period.						
Table 3.2.1	Emissions to air	AR1	See Table AR1 above. Monitoring of point emission to air was undertaken in accordance with the licence.						
Table 3.2.1	Greenhouse gas emissions	None specified	Cumulative Volumes from point sources A8 and A9 have been reported in Table AR1 above.						
Table 3.8.1	Groundwater quality monitoring	GR1	Groundwater quality monitoring was undertaken in accordance with the licence. See Table GR1 above.						
5.1.3	Compliance	AACR	AACR submitted in required template as part of this submission.						
5.1.4	Complaints summary	None specified	Community Reference Group (CRG) meetings are undertaken in Onslow every 4 months. No complaints were received during the reporting period.						

Note 1: Forms are in Schedule 2

Condition 5.2.2: The annual environment report shall also contain:

(a) Any relevant process, production or operational data recorded under Condition 3.1.3;

Refer to Table AR1 which details cumulative flare volumes that are measured via continuous monitoring and results of non-continuous monitoring of point source emissions to air.

(b) An assessment of the information contained within the report against previous monitoring results and Licence limits and/or targets

Groundwater

During the October 2020 Monitoring Event, dissolved chromium was reported in MB01 and MB02 at concentrations consistent with monitoring events from previous years. There are no Marine Waters Groundwater Investigation Levels Criteria (NEPM GILs criteria) for dissolved total chromium. Reported concentrations were consistent with the July 2019 monitoring; data for the nearby Tubridgi Plant indicate that chromium is geochemically present and therefore considered to be naturally occurring in the area.

Copper concentrations have been detected during the 2020 monitoring along with a number of historical monitoring events. Concentrations of copper were reported above the adopted criterion (0.0013 mg/L) in both wells since May 2013, except during the November 2016 monitoring where it was reported below the laboratory Limit of Reporting (LoR) of 0.01 mg/L in both wells. The October 2020 monitoring event observed decreases in copper concentration for both monitoring wells, however both remained above the NEPM Marine Waters GIL criterion.

Nickel concentrations have fluctuated around the LoR in MB01 and MB02 for the duration of the groundwater monitoring program. Nickel was recorded at 0.008 mg/L in MB01 and 0.017 mg/L in MB02 in the October 2020 monitoring, exceeding the NEPM Marine Waters GIL criterion for the monitoring event.

No other dissolved metals were reported above the laboratory limits of reporting and hence the adopted Marine Water criteria (NEPM GIL criteria) in either monitoring well.

TPH concentrations were below the laboratory LoRs in both monitoring wells for the 2020 monitoring event, except for C_{10} - C_{14} fraction TPH in MB02. All other TPH fractions have remained below reporting limits since December 2013.

BTEX concentrations were below the laboratory LoRs in both monitoring wells and has remained so since the May 2013 monitoring.

		Grou	undwater Mc	onitoring		
		ТРН (С10-С14)	ТРН (С15-С28)	ТРН (С29-С36)	Copper	Chromium
		0.05	0.1	0.05	0.001	0.001
Bore	Date	mg/L	mg/L	mg/L	mg/L	mg/L
	9-Apr-14	<0.050	<0.200	<0.200	<0.001	
	19-Nov-14	<0.050	<0.100	<0.050	0.0370	0.025
	16-Nov-15	<0.005	<0.001	<0.005	0.086	0.026
	21-Mar-16	<0.005	<0.001	<0.005	0.009	0.028
MB01	21-Nov-16	<0.005	<0.100	<0.005	<0.010	0.034
	17-Jul-17	<0.050	<0.100	<0.050	0.012	0.035
	30-Jul-18	<0.050	<0.100	<0.050	<0.050	0.028
	8-Jul-19	<0.050	<0.100	<0.050	0.015	0.044
	13-Oct-20	<0.050	<0.100	<0.050	0.008	0.038
	9-Apr-14	<0.050	0.250	0.330	0.002	-
	19-Nov-14	<0.050	0.140	0.330	0.029	<0.01
	16-Nov-15	<0.005	<0.001	0.100	0.024	0.011
	21-Mar-16	<0.005	0.100	0.230	0.039	<0.005
MB02	21-Nov-16	<0.005	<0.100	<0.005	<0.010	0.013
	17-Jul-17	<0.050	<0.100	<0.100	0.012	0.011
	31-Jul-18	<0.050	<0.100	<0.090	<0.050	0.011
	8-Jul-19	<0.050	<0.100	<0.050	0.026	0.011
	13-Oct-20	0.09	<0.100	<0.050	0.021	0.024

Air Emissions

Point source emissions to air from emission points A1 - A7 sampled in October 2020 are compliant with Licence limits. Comparison with previous air emission monitoring results from December 2013, November 2014, September 2015, September 2016, September 2017, August 2018 and August 2019 shows sales gas compressors (sample points A1-A3) air emissions, which implement SoLoNOx technology, are consistent over the years sampled.

Air Emission Monitoring					
		NOx	CO	TOC	
Emission Point	Date	mg/m³	mg/m ³	mg/m³	
A1	13-Dec-13	5	<2	<2	
	26-Nov-14	3.9	6.2	<2	
	17-Sep-15	4.0	2.9	2.1	
	21-Sep-16	5.1	<2	<1	
	14-Sep-17	*	*	*	
	30-Aug-18	10	<2	<2	
	28-Aug-19	<4	<3	<2	
	15-Oct-20	<7	<7	<2	
	11-Dec-13	3.8	2.3	<2	
	25-Nov-14	5.8	<2	<2	
	17-Sep-15	9.2	2.8	<1.0	
A2	20-Sep-16	7.4	2.9	<1	
AZ	14-Sep-17	9.3	2.6	9.5	
	30-Aug-18	14	<2	<2	
	28-Aug-19	6.9	9.1	<2	
	15-Oct-20	<7	<7	<2	
	11-Dec-13	<2	<2	6.4	
	25-Nov-14	6.3	<3	<2	
	17-Sep-15	4.8	2.9	<1.0	
A3	21-Sep-16	8.8	2.8	<1	
	14-Sep-17	5.8	<2	24	
	30-Aug-18	12	3	<2	
	28-Aug-19	<4	4.7	<2	
	14-Oct-20	<7	<7	<2	
	10-Dec-13	40	190	290	
	26-Nov-14	44	330	200	
	18-Sep-15	73	230	180	
	22-Sep-16	56	340	370	
A4	13-Sep-17	NA	NA	NA	
	29-Aug-18	NA	NA	NA	
	28-Aug-19	NA	NA	NA	
	14-Oct-20	66	310	410	
	10-Dec-13	50	180	260	
	26-Nov-14	120	120	180	
	18-Sep-15	95	190	150	
	21-Sep-16	64	230	260	
A5	13-Sep-17	61	280	270	
	29-Aug-18	61	350	340	
	28-Aug-19	37	360	280	
	14-Oct-20	68	240	220	
	10-Dec-13	15	150	190	
A6	25-Nov-14	63	220	180	
	18-Sep-15	57	230	210	
	21-Sep-16	79	240	220	
	13-Sep-17	74	240	250	
	29-Aug-18	53	240	210	
	23-Aug-10	55	240	210	

Air Emission Monitoring						
		NOx	CO	TOC		
Emission Point	Date	mg/m³	mg/m³	mg/m ³		
	28-Aug-19	54	270	200		
	Oct-20	Offline	Offline	Offline		
Α7	12-Dec-13	28	180	260		
	25-Nov-14	60	280	230		
	18-Sep-15	*	*	*		
	22-Sep-16	58	270	270		
	13-Sep-17	57	290	250		
	29-Aug-18	110	290	260		
	28-Aug-19	37	390	300		
	13-Oct-20	93	230	280		

NA Sales Gas Compressor unavailable for testing during the sampling event due to decommissioning.. * Gas Turbine Generator was unavailable for testing during the sampling event due to maintenance.

(a) A list of any original monitoring reports submitted to the licensee from third parties in the reporting period and make these reports available on request.

Report Date	Emission Point	Report Title
13 November 2020	A1 - A7	Report Number R009565r – Annual Emission Monitoring 2020
		Macedon Gas Facility
11 November 2020	MB01 & MB02	Groundwater Quality Monitoring Report – November 2020