

Government of Western Australia Department of Water and Environmental Regulation

Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V Division 3

Once completed, please submit this form either via email to <u>info@dwer.wa.gov.au</u>, or to the below postal address:

Department of Water and Environmental Regulation Locked Bag 10 Joondalup DC WA 6919

Section A – Licence	details					
Licence number:	L8560/2011/2 Licence file number: 2012/006900					
Licence holder name:	City of Kalgoorlie-Boulder					
Trading as:	City of Kalgoorlie-Boulder					
ACN:	ABN 63 711 737 609					
Registered business address:	577 Hannan St, Kalgoorlie WA, 6430					
Reporting period:	01/07/2019 to 30/06/2020					

Section B - Statement of compliance with licence conditions

Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)

 \Box Yes – please complete:

- section C;
- section D (if required); and
- sign the declaration in Section F.

⊠ No – please complete:

- section C;
- section D (if required);
- section E; and
- sign the declaration in Section F.

Section C – Statement of actual production

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category	Actual production quantity	
54	2 203 034 m3/year	
61	3 334 m3/year	

Section D – Statement of actual Part 2 waste discharge quantity

Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.

Prescribed premises category	Actual Part 2 waste discharge quantity	
54 & 61 Combined – Location 4	176.7ML /year	

Department of Water and Environmental Regulation

54 & 61 Combined – Location 8 333 351 m3/year Section E – Details of non-compliance with licence condition Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period. Condition no: 1.2.5 Date(s) of non-compliance: Condition 1.2.5 requires "the integrity of the contaminated infrastructure is maintained" 1/7/2019 – 30/6/2020 Details of non-compliance: Condition 1.2.5 requires "the integrity of the contaminated infrastructure is maintained" Water Balance Investigation report was submitted to the DWER in May 2018; findings were the there is likely leakage from the three lagoons and the Treated Effluent Balance Tank. What was the actual (or suspected) environmental impact of the non-compliance? NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.	Prescribed pren	nises category	Actual Part 2 waste discharge quantity		
54 & 61 Combined – Location 8 333 351 m3/year Section E – Details of non-compliance with licence condition Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period. Condition no: 1.2.5 Date(s) of non-compliance: Condition 1.2.5 requires "the integrity of the contaminated infrastructure is maintained" 1/7/2019 – 30/6/2020 Details of non-compliance: Condition 1.2.5 requires "the integrity of the contaminated infrastructure is maintained" Water Balance Investigation report was submitted to the DWER in May 2018; findings were the there is likely leakage from the three lagoons and the Treated Effluent Balance Tank. What was the actual (or suspected) environmental impact of the non-compliance? NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.	54 & 61 Combine	ed – Location 6	zero		
Section E – Details of non-compliance with licence condition Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period. Condition no: 1.2.5 Date(s) of non-compliance: Condition no: 1.2.5 Date(s) of non-compliance: Details of non-compliance: 1/7/2019 – 30/6/2020 Details of non-compliance: Condition 1.2.5 requires "the integrity of the contaminated infrastructure is maintained" Water Balance Investigation report was submitted to the DWER in May 2018; findings were the there is likely leakage from the three lagoons and the Treated Effluent Balance Tank. What was the actual (or suspected) environmental impact of the non-compliance? NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.	54 & 61 Combined – Location 7		793 078 m3/year		
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period. Condition no: 1.2.5 Date(s) of non-compliance: 1/7/2019 – 30/6/2020 Details of non-compliance: Condition 1.2.5 requires "the integrity of the contaminated infrastructure is maintained" Water Balance Investigation report was submitted to the DWER in May 2018; findings were the there is likely leakage from the three lagoons and the Treated Effluent Balance Tank. What was the actual (or suspected) environmental impact of the non-compliance? NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.	54 & 61 Combined – Location 8		333 351 m3/year		
at a time during the reporting period. Condition no: 1.2.5 Date(s) of non-compliance: 1/7/2019 – 30/6/2020 Details of non-compliance: Condition 1.2.5 requires "the integrity of the contaminated infrastructure is maintained" Water Balance Investigation report was submitted to the DWER in May 2018; findings were the there is likely leakage from the three lagoons and the Treated Effluent Balance Tank. What was the actual (or suspected) environmental impact of the non-compliance? NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.	Section E – De	etails of non-complia	nce with licence condit	ion	
Condition no: 1.2.5 compliance: 1///2019 – 30/6/2020 Details of non-compliance: Condition 1.2.5 requires "the integrity of the contaminated infrastructure is maintained" Water Balance Investigation report was submitted to the DWER in May 2018; findings were the there is likely leakage from the three lagoons and the Treated Effluent Balance Tank. What was the actual (or suspected) environmental impact of the non-compliance? NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.			ndition with which the licend	ce holder was non-compliant	
Details of non-compliance: Condition 1.2.5 requires "the integrity of the contaminated infrastructure is maintained" Water Balance Investigation report was submitted to the DWER in May 2018; findings were the there is likely leakage from the three lagoons and the Treated Effluent Balance Tank. What was the actual (or suspected) environmental impact of the non-compliance? NOTE – please attach maps or diagrams to provide insight into the precise location of where the non- compliance took place.	Condition no:	1.2.5		1/7/2019 - 30/6/2020	
Water Balance Investigation report was submitted to the DWER in May 2018; findings were the there is likely leakage from the three lagoons and the Treated Effluent Balance Tank. What was the actual (or suspected) environmental impact of the non-compliance? NOTE – please attach maps or diagrams to provide insight into the precise location of where the non- compliance took place.	Details of non-co	ompliance:	CONTRACTOR OF THE OWNER	- Louis in Sall	
	there is likely lea What was the ac NOTE – please at	tage from the three lago tual (or suspected) environt tach maps or diagrams to p	oons and the Treated Efflue	ent Balance Tank. n-compliance?	
No Water quality impacts have been observed in monitoring bore groundwater samples.	compliance took n				

The lagoon embankments conditions are deteriorated, as reported in the SBWWTP Water Balance Report (May 2018). The treated Effluent Balance Tank HDPE liner is torn and most likely cause of leakage in the IDEA plant area.

Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:

Water Balance report was completed and a program of infrastructure planning refurbishment works has been developed. See Works Approval W6350/2020/1.

Was this non-compliance previously reported to DWER?

Annual Audit Compliance Report Form (September 2017)

Department of Water and Environmental Regulation

Section E – Details of non-compliance with licence condition				
🔀 Yes, and				
Reported to DWER verbally	Date: / /			
Reported to DWER in writing	Date: 10 / 05 / 2018			

Annual Audit Compliance Report Form (September 2017)

Section F – Declaration

I / We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹.

I / We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature ² :			Signature:	
Name: (printed)			Name: (printed)	
Position:	CIM G	unacé Carlohtte	Position:	
Date:	27/2	3/2020	Date:	
Seal (if signing under seal):		1		

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.