



Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V Division 3

Once completed, please submit this form either via email to info@dwer.wa.gov.au, or to the below postal address:

Department of Water and Environmental Regulation
Locked Bag 10
Joondalup DC WA 6919

Section A – Licence details			
Licence number:	L9166/2018/1	Licence file number:	DER2018/000550-1
Licence holder name:	CW Water Management Group Pty Ltd		
Trading as:	Yelverton Bio Industries		
ACN:	167 178 627		
Registered business address:	26 Brown Street, Busselton		
Reporting period:	06 / 12 / 2024 to 06 / 12 / 2025		

Section B – Statement of compliance with licence conditions
Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)
<input type="checkbox"/> Yes – please complete: <ul style="list-style-type: none">• section C;• section D (if required); and• sign the declaration in Section F.
<input checked="" type="checkbox"/> No – please complete: <ul style="list-style-type: none">• section C;• section D (if required);• section E; and• sign the declaration in Section F.

Section C – Statement of actual production	
Provide the actual production quantity for this reporting period. Supporting documentation is to be attached.	
Prescribed premises category	Actual production quantity
61	0 L

Section D – Statement of actual Part 2 waste discharge quantity	
Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached.	
Prescribed premises category	Actual Part 2 waste discharge quantity
61	0 L

Section E – Details of non-compliance with licence condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	1	Date(s) of non-compliance:	Dec 2024 – Nov 2025
Details of non-compliance:			
Liquid waste treatment facility - Receival and screening tank must: (a) consist of covered unit, constructed above ground of concrete;			
Unit is not covered nor is it above ground.			
What was the actual (or suspected) environmental impact of the non-compliance?			
NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.			
None.			
Cause (or suspected cause) of non-compliance:			
Changes occurred during licence application and construction of plant.			
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:			
Licence amendment submitted 19/04/23 and then withdrawn at Yelverton Bio Industries request on the 15/01/24.			
Was this non-compliance previously reported to DWER?			
<input checked="" type="checkbox"/> Yes, and			
<input checked="" type="checkbox"/> Reported to DWER verbally		Date: 24/ 02 / 2021	
<input type="checkbox"/> Reported to DWER in writing		Date: / /	

Section E – Details of non-compliance with licence condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	1	Date(s) of non-compliance:	Dec 2024 – Nov 2025
Details of non-compliance:			
Liquid waste treatment facility - Receival and screening tank must: (b) Include a primary 5mm wedge wire static screen and secondary 1.4 mm wedge wire static screen;			
The 1.4mm wedge wire static screen has been replaced with a screw press which has a 1.4 mm rotary screen. A further sludge separation step has been included using a soft sludge separator. This where floc separation now takes place.			
What was the actual (or suspected) environmental impact of the non-compliance?			
NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.			
None			
Cause (or suspected cause) of non-compliance:			
Plant equipment and processes have been improved.			
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:			
Licence amendment submitted 19/04/23 and then withdrawn at Yelverton Bio Industries request on the 15/01/24.			
Was this non-compliance previously reported to DWER?			
<input checked="" type="checkbox"/> Yes, and			
<input checked="" type="checkbox"/> Reported to DWER verbally		Date: 24 / 02 /2021	
<input type="checkbox"/> Reported to DWER in writing		Date: / /	

Section E – Details of non-compliance with licence condition

Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.

Condition no:	1	Date(s) of non-compliance:	Dec 2024 – Nov 2025
---------------	---	----------------------------	---------------------

Details of non-compliance:

Liquid waste treat facility - Receival and screening tank must: (m) consist of three treatment trains for the treatment of three separate waste streams (winery wash wastes, septage waste & overflow/stormwater);

For optimum running of the plant, the trains can be separate or mixed depending on the quality of the incoming feed.

What was the actual (or suspected) environmental impact of the non-compliance?

NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.

None

All resulting treated water from different waste streams is mixed in the final irrigation tank.

Cause (or suspected cause) of non-compliance:

Experience and data support mixing of the streams.

Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:

Licence amendment submitted 19/04/23 and then withdrawn at Yelverton Bio Industries request on the 15/01/24.

Was this non-compliance previously reported to DWER?

Yes, and

Reported to DWER verbally

Date: 24 / 02 / 2021

Reported to DWER in writing

Date: / /

Section E – Details of non-compliance with licence condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	1	Date(s) of non-compliance:	Dec 2024 – Nov 2025
Details of non-compliance:			
<p>Sumps – (a) to be kept free of debris/material and at full storage capacity; and (b) all sediments removed from the sumps must be disposed of to a licensed facility.</p> <p>There are no sumps, all liquid is caught in the bunded area and returned to the pit. Any sediment collects in the pit where it is removed and disposed of at a licensed facility.</p>			
<p>What was the actual (or suspected) environmental impact of the non-compliance?</p> <p>NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.</p>			
None			
Cause (or suspected cause) of non-compliance:			
Changes occurred during licence application and construction of plant.			
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:			
Licence amendment submitted 19/04/23 and then withdrawn at Yelverton Bio Industries request on the 15/01/24.			
Was this non-compliance previously reported to DWER?			
<input checked="" type="checkbox"/> Yes, and			
<input checked="" type="checkbox"/> Reported to DWER verbally		Date: 24 / 02 / 2021	
<input type="checkbox"/> Reported to DWER in writing		Date: / /	

Section E – Details of non-compliance with licence condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	1	Date(s) of non-compliance:	Dec 2024 – Nov 2025
Details of non-compliance:			
Piezometers 1 -11. Piezometer 7 is not deep enough to give accurate ground water depth measurements. Irrigation area 7 was irrigated when piezometer 7 did not show ground water depth greater than 2m.			
What was the actual (or suspected) environmental impact of the non-compliance? NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.			
None. Piezometer 7 has been replaced with 7A.			
Cause (or suspected cause) of non-compliance:			
Piezometer 7 not deep enough.			
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:			
Replace piezometer 7 in the licence with 7A.			
Was this non-compliance previously reported to DWER?			
<input type="checkbox"/> Yes, and			
<input type="checkbox"/> Reported to DWER verbally		Date: / /	
<input checked="" type="checkbox"/> Reported to DWER in writing		Date: 31 / 01 / 23	

Section E – Details of non-compliance with licence condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	1	Date(s) of non-compliance:	Dec 2024 – Nov 2025
Details of non-compliance:			
<p>Filtration and irrigation – d) The filtration and irrigation system must consist of:</p> <ul style="list-style-type: none"> • 2 x 5,000L Clarifier tanks and stands • Large/heavy droplet surface irrigation pipework applied to the top of the biosolids (compost) storage area stockpiles, for the discharge of treated liquid waste. <p>The above equipment has never been part of the original nor current design.</p>			
<p>What was the actual (or suspected) environmental impact of the non-compliance?</p> <p>NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.</p>			
None			
Cause (or suspected cause) of non-compliance:			
Unknown			
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:			
Licence amendment submitted 19/04/23 and then withdrawn at Yelverton Bio Industries request on the 15/01/24.			
Was this non-compliance previously reported to DWER?			
<input checked="" type="checkbox"/> Yes, and			
<input checked="" type="checkbox"/> Reported to DWER verbally		Date: 24/ 02 / 21	
<input type="checkbox"/> Reported to DWER in writing		Date: / /	

Section E – Details of non-compliance with licence condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	7	Date(s) of non-compliance:	Dec 2024 – Nov 2025
Details of non-compliance:			
Treat liquid waste water – (sampling from) Outlet pipe of the final tank of the liquid waste treatment system.			
Due to the irrigation set up, sampling is sometimes taken from the final tank. Sampling from the outlet of the final tank is only possible when irrigation area 7 is watered.			
What was the actual (or suspected) environmental impact of the non-compliance?			
NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.			
None			
Cause (or suspected cause) of non-compliance:			
Irrigation set up is not sampling friendly.			
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:			
Correct sampling procedures are followed when sampling from the tank to ensure it is a representative sample.			
Was this non-compliance previously reported to DWER?			
<input checked="" type="checkbox"/> Yes, and			
<input type="checkbox"/> Reported to DWER verbally		Date: / /	
<input checked="" type="checkbox"/> Reported to DWER in writing		Date: 31 / 01 / 23	

Section E – Details of non-compliance with licence condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	14(d)	Date(s) of non-compliance:	Dec 2024 – Nov 2025
Details of non-compliance:			
Actual plant growth was not recorded against total nutrient plant uptake			
What was the actual (or suspected) environmental impact of the non-compliance? NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.			
None			
Cause (or suspected cause) of non-compliance:			
Impossible to achieve. Plants are grown for their ornamental value, not volume/mass growth. Species grown are varied which adds to the complexity.			
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:			
Licence amendment submitted 19/04/23 and then withdrawn at Yelverton Bio Industries request on the 15/01/24.			
Was this non-compliance previously reported to DWER?			
<input checked="" type="checkbox"/> Yes, and			
<input type="checkbox"/> Reported to DWER verbally		Date:	
<input checked="" type="checkbox"/> Reported to DWER in writing		Date: 31 / 01 / 23	

Section E – Details of non-compliance with licence condition			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.			
Condition no:	9	Date(s) of non-compliance:	Dec 2024 – Nov 2025
Details of non-compliance:			
Volumetric flow rate for each waste type received.			
Volume delivered is determined by CWTF.			
What was the actual (or suspected) environmental impact of the non-compliance?			
NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.			
None			
Cause (or suspected cause) of non-compliance:			
No suitable equipment to measure flow rate.			
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:			
Licence amendment submitted 19/04/23 and then withdrawn at Yelverton Bio Industries request on the 15/01/24.			
Was this non-compliance previously reported to DWER?			
<input checked="" type="checkbox"/> Yes, and			
<input checked="" type="checkbox"/> Reported to DWER verbally		Date: 24 / 02 / 21	
<input type="checkbox"/> Reported to DWER in writing		Date: / /	

Section F – Declaration

<p>I / We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹.</p> <p>I / We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.</p>			
Signature ² :	[REDACTED]	Signature:	
Name: (printed)		Name: (printed)	
Position:		Position:	
Date:		6.5.2026	Date:
Seal (if signing under seal):			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.