

Annual Audit Compliance Report Form

Environmental Protection Act 1986, Part V Division 3

Once completed, please submit this form either via email to info@dwer.wa.gov.au, or to the below postal address:

Department of Water and Environmental Regulation Locked Bag 10 Joondalup DC WA 6919

Section A – Licence details				
Licence number:	L9293/2021/1	Licence file number:	DER2021/000158	
Licence holder name:	Silver Lake (Rothsay) Pty Ltd			
Trading as:	Silver Lake Resources Pty Ltd			
ACN:	151 137 450			
Registered business address:	Suite 4, Level 3 South Shore Centre, 85 South Perth Esplanade, South Perth WA 6151			
Reporting period:	01/01/2022 to 31/12/2022			

Section B – Statement of compliance with licence conditions Did you comply with all of your licence conditions during the reporting period? (please tick the appropriate box)				
 No – please complete: section C; section D (if required); section E; and sign the declaration in Section E 				

Provide the actual production quantity for this reporting period. Supporting documentation is to be attached. Prescribed premises category Actual production quantity

Section D – Statement of actual Part 2 waste discharge quantity Provide the actual Part 2 waste discharge quantity for this reporting period. Supporting documentation is to be attached. Prescribed premises category Actual Part 2 waste discharge quantity Category 6: Mine dewatering Category 64: Class II or III putrescible landfill site Category 85: Sewerage facility 23 m³/day

Section E – Deta	ils of non-compliance wi	th licence condition	1			
Please use a separate page for each condition with which the licence holder was non-compliant at a time during the reporting period.						
Condition no:	14	Date(s) of non- compliance:	14/03/2022, 7/06/2022			
Details of non-compliance:						
Water quality results from location RYMP2 were not completed quarterly as specified in L9293 Table 11 due to a failure of the bore pump (March and June 2022).						
What was the actua	al (or suspected) environmen	tal impact of the non-c	ompliance?			
NOTE – please attach maps or diagrams to provide insight into the precise location of where the non-compliance took place.						
No environmental impact from non-compliance						
Cause (or suspected	ed cause) of non-compliance:					
Failure of bore infrastructure preventing sampling.						
Action taken to mitigate any adverse effects of non-compliance and prevent recurrence of the non-compliance:						
The pump was rectified in September 2022 and sampling resumed.						
Was this non-compliance previously reported to DWER?						
☐ Yes, and						
Reported to	DWER verbally	Date: / /				
Reported to	DWER in writing	Date: / /				

Department of Water and Environmental Regulation

Section F - Declaration

I / We declare that the information in this Annual Audit Compliance Report is true and correct and is not false or misleading in a material particular¹.

I / We consent to the Annual Audit Compliance Report being published on the Department of Water and Environmental Regulation's (DWER) website.

Signature ² :		Signature:	
Name: (printed)		Name: (printed)	
Position:	Mine Manager	Position:	
Date:	27/02/2023	Date:	
Seal (if signing under seal):			

¹ It is an offence under section 112 of the *Environmental Protection Act 1986* for a person to give information on this form that to their knowledge is false or misleading in a material particular.

² AACRs can only be signed by the licence holder or an authorised person with the legal authority to sign on behalf of the licence holder.